



UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

NO. N 89-28-12-1

To the following Permittee or Operator:

Name Consolidation Coal Company

Mine Emery Deep  Surface  Underground  Other

County Emery State Utah Telephone \_\_\_\_\_

Mailing Address P.O. Box 527 Emery Utah 84522

State Permit No. ACT/015/015

Ownership Category  State  Federal  Fee  Mixed

Date of inspection December 19, 19 89

Time of inspection 10:00  a.m.  p.m. to 2:30  a.m.  p.m.

Operator Name (other than Permittee) \_\_\_\_\_

Mailing Address \_\_\_\_\_

notice of violation

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining is**  is not  expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/ mailing December 19, 1989 Time of service/ mailing 2:45  a.m.  p.m.

Chris Jones  
Permittee/Operator representative  
[Signature] 12-19-89  
Signature

Mine Engineer  
Title

Daron Haddock  
Division of Oil, Gas & Mining representative  
Daron R. Haddock  
Signature

Reclamation Specialist  
Title  
#28  
Identification Number

SEE REVERSE SIDE

WHITE-DOG M YELLOW-OS M PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE



### NOTICE OF VIOLATION NO. N 89-28-12-1

Violation No. 1 of 1

Nature of violation

Failure to maintain diversions in a  
manner which prevents additional contributions  
of suspended solids to streamflow & to run off  
outside the permit area,

Provisions of act, regulations or permit violated

UMC 817.43

Portion of operation to which notice applies

Diversions around upper Coal Yard Stockpile,  
(North West of Mine yard)

Remedial action required (including any interim steps)

Redefine the berm around the coal yard,  
Clean the ditch around the base of the  
coal yard.

Abatement time (including interim steps)

January 18, 1990