



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

[Handwritten signature] *SCC*

Norman H. Bangerter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: August 9, 1989
10:30am - 1:10pm

Permittee and/or Operators Name: Consolidation Coal Company
Business Address: P.O. Box 527, Emery, Utah 84522
Mine Name: Emery Deep Permit Number: ACT/015/015
Type of Mining Activity: Underground Surface Other
County: Emery
Company Official (s): Chris Jones
State Official(s): Lynn Kunzler
Partial: Complete: Date of Last Inspection: July 5, 1989
Weather Conditions: partly cloudy
Acreage: Permitted 5180 Disturbed 40 Regraded 2.66 Seeded 2.66 Bonded 247
Enforcement Action: None.

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	(X)	()	()	(X)
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(X)	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	(X)	()	()	(X)
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/015

DATE OF INSPECTION: 08/09/89

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permits. The Division approved the underground waste disposal plans on June 23, 1989. The mine had not yet been notified of this approval. A copy of the approval was sent. The coal fines minimization plan was approved on June 23, 1989. Materials have been ordered but not received. Mr. Jones indicated that the silt fence would be installed as soon as the materials were received. Coal fines accumulation were measured in the target area for the minimization plan and were found to be below the approved accumulation level of 2 inches which indicates when they would be vacuumed. Mr. Jones was informed that should the fines accumulate to the 2" level, they would need to be cleaned up regardless of whether the fence materials had been delivered and the fence erected.


2. Signs and Markers. The topsoil and subsoil stockpiles associated with the construction of the new borehole pump facilities have been bermed and an appropriate identification signs have been installed.

13. Revegetation. The operator has seeded the disturbed areas associated with the construction of the new borehole pump facilities. However, due to drought conditions vegetation has not yet established. Close inspection of the site showed the soil materials were stable with no apparent accelerated erosion.

Copy of this Report:

Mailed to: Brian Smith - OSM, Chris Jones - Consol, PFO

Given to: Joe Helfrich & Sue Linner - DOGM

Inspectors Signature and Number:  #17 Date: 08/22/89