

7065



0021

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

gdr *SCC*

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: April 7, 1989
10:30 a.m. to 12:40 p.m.

Permittee and/or Operators Name: Consolidation Coal Company
Business Address: P.O. Box 527 Emery, Utah 84522
Mine Name: Emery Deep Permit Number: ACT/015/015
Type of Mining Activity: Underground Surface Other
County: Emery State: Utah
Company Official(s): Chris Jones
State Official(s): Daron Haddock
Partial: XX Complete Date of Last Inspection: March 7, 1989
Weather Conditions: Sunny, warm, breezy
Acreage: Permitted 5180 Disturbed 40 Regraded 2.66 Seeded 2.66 Bonded 247
Enforcement Action: NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	(X)
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	(X)	()	()	(X)
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	(X)	()	()	(X)
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	(X)	()	()	(X)
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/015

DATE OF INSPECTION April 7, 1989

(Comments are Numbered to Correspond with Topics Listed Above)

2. SIGNS AND MARKERS:

New mine identification signs have been placed at points of public access to the newly constructed sediment pond and borehole area. Disturbed area perimeter markers are also in place in these areas. Topsoil markers will be placed on the recently formed piles after they are seeded which is scheduled for this afternoon.

4c. SEDIMENT PONDS AND IMPOUNDMENTS:

Construction of the new mine discharge pond is complete with the exception of seeding the embankments which should be done soon. The operator is now waiting for power to be installed to the borehole.

6. DEVELOPMENT WASTE AND SPOIL DISPOSAL:

The temporary waste disposal pile has recently been pushed to the side of the storage pad and recompactd to allow for more coal storage space.

13. REVEGETATION:

All areas disturbed in recent construction are scheduled for seeding. Most seeding will be done with a drill, however, small inaccessible areas may be hand broadcast.

15. CESSATION OF OPERATIONS:

Due to market conditions the operator is considering going into a temporary cessation of operations. At the present time coal is being stock piled and the mine may shut down within a month. Mr. Jones was aware of the requirement to file notice of cessation with the division as outlined in UMC 817.131.

Copy of this report:

Mailed to: Chris Jones

Mailed to SLC for: Brian Smith, OSM Joe Helfrich, DOGM

File to: PFO

Daron R. Haddock

Inspectors Signature and Number Daron R. Haddock #28 Date April 11, 1989