

0007



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangertter

Governor

Dee C. Hansen

Executive Director

Dianne R. Nielson, Ph.D.

Division Director

355 West North Temple

3 Triad Center, Suite 350

Salt Lake City, Utah 84180-1203

801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: June 19, 1990
11:00am - 1:30pm

Permittee and/or Operators Name: Consolidation Coal Company
Business Address: P.O. Box 527, Emery, Utah 84522
Mine Name: Emery Deep Permit Number: ACT/015/015
Type of Mining Activity: Underground Surface Other
County: Emery
Company Official (s): Dee Bray
State Official(s): Lynn Kunzler
Partial: Complete: Date of Last Inspection: May 30, 1990
Weather Conditions: Clear and warm
Acreage: Permitted 5180 Disturbed 40 Regraded 2.66 Seeded 2.66 Bonded 247
Enforcement Action: None.

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	()	()	()
b. DIVERSIONS	(X)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	(X)	()	()	()
f. EFFLUENT LIMITATIONS	(X)	()	()	()
5. EXPLOSIVES	(X)	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	(X)	()	()	(X)
7. COAL PROCESSING WASTE	(X)	()	()	()
8. NONCOAL WASTE	(X)	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(X)	()	()	()
10. SLIDES AND OTHER DAMAGE	(X)	()	()	()
11. CONTEMPORANEOUS RECLAMATION	(X)	()	()	()
12. BACKFILLING AND GRADING	(X)	()	()	()
13. REVEGETATION	(X)	()	()	(X)
14. SUBSIDENCE CONTROL	(X)	()	()	()
15. CESSATION OF OPERATIONS	(X)	()	()	(X)
16. ROADS				
a. CONSTRUCTION	(X)	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	(X)	()	()	()
d. MAINTENANCE	(X)	()	()	()
17. OTHER TRANSPORTATION FACILITIES	(X)	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	(X)	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/015

DATE OF INSPECTION: 06/19/90

(Comments are Numbered to Correspond with Topics Listed Above)

4e. Surface and Groundwater Monitoring. Water monitoring reports were inspected for the period March through May. Everything was in order with no exceedences being reported.

6. Disposal of Development Waste and Spoil. Consol has not yet constructed their approved permanent waste disposal site. In discussing this with their office in Saint Louis over the phone, it was indicated that their temporary cessation may become permanent, in which case they would prefer to use existing waste for backfill rather than disturbing an additional area for disposal. If the site is re-activated they would then construct the permanent disposal site. This will be discussed in more detail in the temporary cessation letter that is forth coming. The refuse pile inspections were current through June 13, 1990, with no problems noted.

13. Revegetation. The appropriate vegetation reference areas were located in the field and locations checked on the vegetation map. All reference areas were easily located in the field. However, the mixed desert shrub reference area was not correctly marked on the map. This will be corrected and submitted with the repermit package in the near future. All reference areas had been fenced with barbed wire.

15. Cessation of Operations. The mine was inactive at the time of this inspection and it was indicated that it would remain so for some time. The operator was reminded of his responsibility to notify the Division in writing of the cessation and to identify the activities that would be on-going until the mine is reactivated.

Copy of this Report:

Mailed to: Brian Smith - OSM, Dee Bray, Consol, PFO

Given to: Joe Helfrich & Daron Haddock - DOGM

Inspectors Signature and Number:  #17 Date: 07/06/90