



Norman H. Bangerter  
Governor

Dee C. Hansen  
Executive Director

Dianne R. Nielson, Ph.D.  
Division Director

# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

*John A. Z*

## INSPECTION REPORT

PERMIT NO.: ACT/015/015 Inspection Date: June 12, 1991  
 Permittee and/or Operators Name: Consolidation Coal  
 Business Address: P.O. Box 527  
 City: Emery State: Utah Zip: 84522  
 Mine Name: Consolidation Coal  
 County: Emery State: Utah  
 Type of Mining Activity: Underground XX Surface Other  
 Company Official (s): Dee Bray  
 State Officials (s): Stephen J. Demczak (DOGM)  
 Time of Inspection: 8:00 (X)a.m. ( ) p.m. to 12:01 ( )a.m. (X) p.m.  
 Partial Complete: XX Date of Last Inspection: May 30, 1991  
 Weather Conditions: Clear/Warm 70's  
 Acreage: Permitted 5180 Disturbed 40 Regraded 2.7 Seeded 2.7  
 Bonded 247 Enforcement Action: None

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( X )	( )	( )	( X )
2. SIGNS AND MARKERS	( X )	( )	( )	( )
3. TOPSOIL	( X )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( X )	( )	( )	( )
b. DIVERSIONS	( X )	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( X )	( )	( )	( X )
d. OTHER SEDIMENT CONTROL MEASURES	( X )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( X )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( X )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( X )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( X )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( X )	( )
8. NONCOAL WASTE	( X )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( X )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( X )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( X )	( )	( )	( )
12. BACKFILLING AND GRADING	( X )	( )	( )	( )
13. REVEGETATION	( X )	( )	( )	( )
14. SUBSIDENCE CONTROL	( X )	( )	( )	( )
15. CESSATION OF OPERATIONS	( X )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( X )	( )	( )	( )
b. DRAINAGE CONTROLS	( X )	( )	( )	( )
c. SURFACING	( X )	( )	( )	( )
d. MAINTENANCE	( X )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( X )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( X )	( )	( )	( )

INSPECTION REPORT COMMENTS  
(continuation sheet)

Page 2 of 2

PERMIT NO. ACT/015/015 INSPECTION DATE June 12, 1991

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMIT:

- (a) The surface facilities map was reviewed and compared with the field inspection. The map was correct. There is one area which needs additional detail. This information will be submitted to DOGM with an up-dated surface facilities map.
- (b) An AVS check in the field was made. There were no changes in status.

2. SIGNS & MARKERS:

Signs were located at the entrances to the mine permit areas. All perimeter markers at the mine site were painted.

4. HYDROLOGIC BALANCE:

c. Sediment Ponds and Impoundments:

The NPDES report for ponds was inspected for First Quarter and no problems were noted. Samples were taken for Second Quarter on 6/3/91. Pond #1 and #6 were discharging at the time of this inspection. These ponds are used to discharge mine water by means of pumps; therefore, the ponds are not used for storing and discharging surface drainage.

e. Surface and Groundwater Monitoring:

Wells and spring water samples were taken 6/3/91.

6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL DISPOSAL:

Coal Refuge was inspected 3/1/91 with no problems noted pertaining to the waste pile.

Copy of report:

Mailed to: Consolidation Coal Co.  
Mailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)  
Filed to: PFO

Inspectors Signature and Number: Stephen J. Demczak #39  
Date: 6/19/91

*Stephen J. Demczak*