0004

**Consolidation Coal Company**
Emery Mine
P. O. Box 527
Emery, Utah 84522
(801) 286-2301

Mr. Daron R. Haddock
Permit Supervisor
Division of Oil, Gas, and Mining
1594 West North Temple, Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801

7 April 1999

ACT/015/015
#6

RE: Emery Temp. Coal Stockpile Inspection Report

Dear Mr. Haddock:

Enclosed is the 1st Qtr. Inspection Form of the Temp. Coal Stockpile, where the waste rock is being stored, at the Emery Mine. The form has been certified by a registered P.E. from our Sessor office.

If you have any questions please call me at (435) 286-2301.

Sincerely,

Stephen R. Behling

Stephen R. Behling
General Mine Foreman
Emery Mine

attachments: Inspection Form certified by a P.E.

RECEIVED
APR 9 1999
DIV. OF OIL, GAS & MINING

# INSPECTION FORM

## COAL REFUSE PILES AND COAL WASTE IMPOUNDMENTS

Name STEPHEN R. BEHLING Title GENERAL MINE FOREMAN

Date 3-16-99 Date last inspected 12-2-98

Site Name EMERY TEMP. COAL STOCKPILE Mine Name EMERY

Refuse Facility ID # 1211-UT-09-00079-01

Refuse piles---Part A only
Impoundments---Part A and Part B

### Part A

| | | | |
|---|---|---|---|
| 1. | Foundation preparation (vegetation, topsoil removal?) | ✓ Yes | ___ No |
| 2. | Lift Thickness (inches) | ___ | |
| 3. | Compaction (4 to 6 complete passes) | ___ Yes | ✓ No |
| 4. | Burning* (specify extent and location) | ___ Yes | ✓ No |
| 5. | Angle of Slope (degrees) | N/A | ___ |
| 6. | Seepage* (specify location, color, & appr. volume | ___ Yes | ✓ No |
| 7. | Cracks or scarps* (location, size) | ___ Yes | ✓ No |
| 8. | Major erosion problems* (location and extent) | ___ Yes | ✓ No |
| 9. | Water impounding against toe* | ___ Yes | ✓ No |

### Part B

| | | | |
|---|---|---|---|
| 10. | Embankment freeboard (feet) | ___ | |
| 11. | ____Increase____Decrease in water level (feet) | ___ Yes | ___ No |
| 12. | Sumps or sinkholes in slurry surface | ___ Yes | ___ No |
| 13. | Clogging* (pipes, ditches, spillway) | ___ Yes | ___ No |
| 14. | Trash racks clear and in place | ___ Yes | ___ No |

* Adverse conditions noted in these items should be described (extent, location, volume, etc.) in the space provided. Major adverse changes could cause instability.

| Inspection Category | Comments |
|---|---|
| | NO PROBLEMS EVIDENT |
| | NO HAZARDOUS CONDITIONS WERE FOUND |

BRIAN BUTTS
062-045924
REGISTERED PROFESSIONAL ENGINEER
STATE OF ILLINOIS

3/29/99

FORM 1