



State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

Representatives Present During the Inspection:

Company	Russell Hardy
OGM	Karl Houskeeper Environmental Scientist III

Inspection Report

Permit Number:	C0150015
Inspection Type:	COMPLETE
Inspection Date:	Thursday, April 12, 2007
Start Date/Time:	4/12/2007 8:00:00 AM
End Date/Time:	4/12/2007 3:00:00 PM
Last Inspection:	Thursday, March 15, 2007

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Overcast/Light Showers, Temp. 46 Deg. F.

InspectionID Report Number: 1265

Accepted by: pgrubaug 
4/30/2007

Permitee: **CONSOLIDATION COAL CO**

Operator: **CONSOLIDATION COAL CO SESSER OPERATIONS**

Site: **EMERY DEEP MINE**

Address: **PO BOX 566, SESSER IL 62884**

County: **EMERY**

Permit Type: **PERMANENT COAL PROGRAM**

Permit Status: **ACTIVE**

Current Acreages

5,568.00	Total Permitted
62.50	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- Federal
 State
 County
 Fee
 Other

Types of Operations


- Underground
 Surface
 Loadout
 Processing
 Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Permit Conditions: Emery Deep has one permit condition. The permittee must submit water quality data in an electronic format through the Electronic Data Input web site.

No violations pending.

Inspector's Signature: _____



Date Thursday, April 12, 2007

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
 telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

Permit Number: C0150015
 Inspection Type: COMPLETE
 Inspection Date: Thursday, April 12, 2007

Inspection Continuation Sheet

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

The current DOGM permit C/015/015 was issued effective 01/06/2006 and expires 01/08/2011.

-Certificate of Insurance policy number BOG 9377 215-03, issued 11/05/2006 and terminates 11/05/2007.

-UPDES permit UT-0022616 effective 12/01/2006 and expires @ midnight 11/30/2011.

-Air Quality permit DAQE-AN0229006-05, issued July 20, 2005.

-SPCC Plan dated 10/24/06. The Plan is P.E. certified, stamped, signed and dated by a Utah P.E.

2. Signs and Markers

The mine ID sign is in place and contains the required information.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The last sediment pond's inspections were done on 03/12/2007. No problems were noted.

4.d Hydrologic Balance: Water Monitoring

Fourth quarter 2006 water monitoring is in the EDI website and has been uploaded. Water monitoring is current.

7. Coal Mine Waste, Refuse Piles, Impoundments

The area where the underground development waste or refuse is stored contains a sign that lists the area as a refuse pile. However, confusion exists in the MRP as this location is listed as a temporary storage area for underground development waste. Further research needs to be done within the MRP. Material from this area was shipped to Headwaters in Wellington, Utah. The truck tickets show that 612.98 tons of material were removed from the site. Another 362 tons of high ash coal were taken from the old tipple area to Headwaters. The Division allowed Emery Deep to ship 1000 tons of refuse from their permitted facility to Headwaters in Wellington. The material is ultimately to be used for a test burn to see if the material is marketable.

As of this inspection, Emery Deep has no plans to pursue the marketing of this material beyond the 1000 tons for a test burn.

20. Air Quality Permit

The Air Quality Permit Approval Order DAQE-AN0229006-05 was issued on July 20, 2005. The permit remains effective.

Permit Number: C0150015
Inspection Type: COMPLETE
Inspection Date: Thursday, April 12, 2007

Inspection Continuation Sheet

Page 4 of 4

21. Bonding and Insurance

Bond #188617, May 3, 1991 and signed August 30, 2005. Bond amount was \$3,454,443.00 was revised to \$2,208,000.00 on July 23, 2004.