



State of Utah
Department of
Natural Resources

MICHAEL R. STYLER
Executive Director

Division of
Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

Representatives Present During the Inspection:	
Company	Russell Hardy
OGM	Karl Houskeeper Environmental Scientist III
Company	Ian McClain Associate Engineer

Inspection Report

Permit Number:	C0150015
Inspection Type:	COMPLETE
Inspection Date:	Tuesday, December 02, 2008
Start Date/Time:	12/2/2008 7:30:00 AM
End Date/Time:	12/2/2008 1:15:00 PM
Last Inspection:	Tuesday, November 04, 2008

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 42 Deg. F.

InspectionID Report Number: 1851

Accepted by: jhelfric
 12/9/2008

Permitee: **CONSOLIDATION COAL CO**
 Operator: **CONSOLIDATION COAL CO SESSER OPERATIONS**
 Site: **EMERY DEEP MINE**
 Address: **PO BOX 566, SESSER IL 62884**
 County: **EMERY**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **ACTIVE**

Current Acreages

5,568.00	Total Permitted
62.50	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Ian McClain, engineer Consol, accompanied Russell Hardy, Consol, and I on the complete inspection.

Permit Conditions: Emery Deep has one permit condition. The permittee must submit water quality data in an electronic format through the Electronic Data Input web site. This condition is being met.

Inspector's Signature: _____

Karl Houskeeper
 Karl Houskeeper, Environmental Scientist III

Date Tuesday, December 02, 2008

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0150015
 Inspection Type: COMPLETE
 Inspection Date: Tuesday, December 02, 2008

Inspection Continuation Sheet

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

The current DOGM permit C/015/015 was issued effective 01/06/2006 and expires 01/08/2011.

-Certificate of Insurance policy number BOG 9377 215-04, issued 11/05/2007 and terminates 01/05/2009.

-UPDES permit UT-0022616 effective 12/01/2006 and expires @ midnight 11/30/2011.

-Air Quality permit DAQE-AN0229006-05, issued July 20, 2005.

-SPCC Plan dated 10/24/06. The Plan is P.E. certified, stamped, signed and dated by a Utah P.E.

2. Signs and Markers

The mine ID signs are in place and contain the required information.

4.a Hydrologic Balance: Diversions

The diversion that runs behind the new oil storage building at the 4th East Portal area is open and functioning, but needs to be graded so that water in the diversion does not collect against the culvert outlet. In winter conditions this can cause the stored water to freeze and block the diversion and/or culvert.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Second quarter pond inspections were done on 09/30/2008.

4.d Hydrologic Balance: Water Monitoring

Second quarter 2008 water monitoring information is in the EDI website and has been uploaded. Water monitoring is current.

4.e Hydrologic Balance: Effluent Limitations

September and October discharge monitoring reports were reviewed. Ponds 2, 4, 5, 6, 7, 8, and 9 did not discharge. Ponds 1 and 3 did discharge. All three months showed that the max loading for TDS was exceeded. DEQ was notified of all the events and the condition is under review.

7. Coal Mine Waste, Refuse Piles, Impoundments

The third quarter refuse pile inspection was done on 08/19/2008 and P.E. certified.

18. Support Facilities, Utility Installations

Work is still taking place on the new oil storage building at the 4th east portal area.

20. Air Quality Permit

The Air Quality Permit Approval Order DAQE-AN0229006-05 was issued on July 20, 2005. The permit remains effective.

Permit Number: C0150015
Inspection Type: COMPLETE
Inspection Date: Tuesday, December 02, 2008

Inspection Continuation Sheet

Page 4 of 4

21. Bonding and Insurance

Bond #188617, May 3, 1991 and signed August 30, 2005. Bond amount was \$3,454,443.00 was revised to \$2,208,000.00 on July 23, 2004.