



# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

### Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

# Inspection Report

Permit Number:	C0150015
Inspection Type:	PARTIAL
Inspection Date:	Wednesday, December 09, 2015
Start Date/Time:	12/9/2015 10:00:00 AM
End Date/Time:	12/9/2015 1:00:00 PM
Last Inspection:	Tuesday, November 10, 2015

Representatives Present During the Inspection:	
OGM	Steve Demczak
Company	Russel Jensen

Inspector: Steve Demczak

Weather: Snow covered, Temp 20's

InspectionID Report Number: 5390

Accepted by: JHELFRIC

1/11/2016

Permittee: **CONSOL MINING COMPANY, LLC**  
 Operator: **CONSOL MINING COMPANY, LLC**  
 Site: **EMERY DEEP MINE**  
 Address: **1000 CONSOL ENERGY DRIVE, CANONSBURG PA 15317**  
 County: **EMERY**  
 Permit Type: **PERMANENT COAL PROGRAM**  
 Permit Status: **INACTIVE**

#### Current Acreages

442.50	<b>Total Permitted</b>
248.50	<b>Total Disturbed</b>
	<b>Phase I</b>
	<b>Phase II</b>
	<b>Phase III</b>

#### Mineral Ownership

- Federal
- State
- County
- Fee
- Other

#### Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

#### Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The mine is inactive. The Emery Deep mine site has been recently sold to Bronco Utah Operations LLC. An application for a permit transfer has been submitted to the Division. Currently the permit is still under Consol. The inspection was conducted with Russel Jensen a Consol employee.

Stephen J. Demczak

Inspector's Signature:

Steve Demczak,  
Inspector ID Number: 39

Date Monday, December 14, 2015



**REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS**

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**1. Permits, Change, Transfer, Renewal, Sale**

There are no permitting actions with the Division at this time.

**2. Signs and Markers**

The identification signs at the gates meet the minimum requirements of the R645 Coal Rules. They are located at the main gates to the property. See Pictures.

**3. Topsoil**

The topsoil piles were inspected, and, there were no signs or wind and water erosion. It appears that mainly weeds are growing on the two areas recently resign and reseeded.

**4.a Hydrologic Balance: Diversions**

The diversions and culverts were open with no water flow. There was some snow in several of the diversions.

**4.b Hydrologic Balance: Sediment Ponds and Impoundments**

The 4th East portal sediment pond and the storage yard sediment pond are near or at the 60% sediment level. These ponds will need to be clean out in the near future. The sediment ponds were inspected with no hazardous conditions noticed. No sediment pond was discharging during the inspection. It is highly unlikely these ponds will discharge.

**4.c Hydrologic Balance: Other Sediment Control Measures**

The silt fences at the 4th east portals are in good condition and functioning as design.

**7. Coal Mine Waste, Refuse Piles, Impoundments**

I inspected the refuse pile with no hazardous conditions notice. This pile is very small.

**8. Noncoal Waste**

The mine site was clear of non-coal waste materials.

**10. Slides and Other Damage**

No slides or other damage was notice during the inspection.

**15. Cessation of Operations**

It is rumor that the property will be sold in the near future. Currently the mine is idle and only maintenance activity is taken place.

**16.a Roads: Construction, Maintenance, Surfacing**

Roads were in good condition.

Permit Number: C0150015  
Inspection Type: PARTIAL  
Inspection Date: Wednesday, December 09, 2015

**16.b Roads: Drainage Controls**

Road diversions and culverts were open.









**CONSOL ENERGY**  
EMERY MINE

CONSOL ENERGY  
EMERY MINE  
PO BOX 527  
EMERY, UT 84522

UTAH STATE MINING PERMIT  
ACT 015-015  
M.S.H.A. ID 42-00079  
PHONE 435-286-2301

**ALL VISITORS MUST  
REGISTER AT MINE OFFICE**

