

Document Information Form

Mine Number: C/015/017

File Name: Internal

To: DOGM

From:

Person N/A

Company N/A

Date Sent: JUNE 30, 1982

Explanation:

INSPECTION MEMO TO COAL FILE

cc:

File in:
C/015, 017, Internal

Refer to:

- Confidential
- Shelf
- Expandable

Date _____ For additional information

June 30, 1982

Inspection Memo
to Coal File

RE: Utah Power & Light
Des-Bee-Dove Mine
ACT/015/017
Emery County, Utah

DATE: June 17, 1982
TIME: 1:30 p.m. - 5:45 p.m.
WEATHER: Fair and windy
COMPANY OFFICIAL: Val Payne
STATE OFFICIALS: Dave Lof and Bart Kale

Compliance with Permanent Performance Standards

771 et al Permits

The operator has received the following approvals:

1. Interim approval from the Division dated May 11, 1978.
2. A waste rock disposal site approval (w/stipulations) was granted on September 28, 1981. The operators response was received by the Division and final approval given on March 24, 1982.

817.11 Signs and Markers

The entrance sign was in place and contained all the pertinent information. Permit area boundary markers were clearly visible around the perimeter.

817.42 - .55 Hydrologic Balance

Surface grading of the Beehive/Little Dove pad has been accomplished to direct and drain runoff into the Beehive portal according to design. Much improvement was noted since the last inspection, however, some ponding was noted under the Little Dove conveyer.

At the south end of the pad
could lead to an erosional problem
completed by the next inspection

racking and
ould be

File in:

- Confidential
 Shelf
 Expandable

Refer to Record No 0008 Date _____

In CI 015, 017, Internal

For additional information

June 30, 1982

Inspection Memo
to Coal File

RE: Utah Power & Light
Des-Bee-Dove Mine
ACT/015/017
Emery County, Utah

DATE: June 17, 1982
TIME: 1:30 p.m. - 5:45 p.m.
WEATHER: Fair and windy
COMPANY OFFICIAL: Val Payne
STATE OFFICIALS: Dave Lof and Bart Kale

Compliance with Permanent Performance Standards

771 et al Permits

The operator has received the following approvals:

1. Interim approval from the Division dated May 11, 1978.
2. A waste rock disposal site approval (w/stipulations) was granted on September 28, 1981. The operators response was received by the Division and final approval given on March 24, 1982.

817.11 Signs and Markers

The entrance sign was in place and contained all the pertinent information. Permit area boundary markers were clearly visible around the perimeter.

817.42 - .55 Hydrologic Balance

Surface grading of the Beehive/Little Dove pad has been accomplished to direct and drain runoff into the Beehive portal according to design. Much improvement was noted since the last inspection, however, some ponding was noted under the Little Dove conveyer.

At the south end of the parking lot the asphalt curbing is cracking and could lead to an erosional problem on the downslope. Repairs should be completed by the next inspection.

INSPECTION MEMO
ACT/015/017
June 30, 1982
Page 2

Drop drains were being installed on the Deseret Pad. The new drainage system should be completed during the miners vacation period.

The culvert at the base of the road from the tippie to the bathhouse pad needs to be cleaned prior to the next inspection.

817.52 Surface and Ground Water Monitoring

The operator was issued NPDES permit UT-0023591 by the EPA on March 29, 1982, the permit expires on December 31, 1986. The permit allows discharge from the sediment pond into Grimes Wash. Water monitoring data was on file up to March 24, 1982.

817.71 - .73 Disposal of Underground Development Waste and Excess Spoil and Non-Acid, Nontoxic-forming Coal Processing Waste

As was mentioned in the permits section, the operator has received final approval for a waste rock disposal site in conjunction with the Wilberg Mine. This site has yet to be developed.

817.89 Disposal of Non-Coal Wastes

On the downslope from the main access road to the Picking Table, a fair amount of scrap metal was noted. It was suggested that it may be to the operators advantage to haul it away as soon as they are able, in order to circumvent a major scrap metal salvage program.

Trash is being placed in concrete bins, one on the Deseret pad and one on the Beehive pad.

817.97 Protection of Fish, Wildlife and Related Environmental Values

In a letter dated April 29, 1982, Utah Power and Light stated that it conforms to guidelines (as put forth in the Raptor Research Report #4, Raptor Research Foundation Inc., 1981) to minimize the possibility of raptor electrocution.

817.121 - .126 Subsidence Control

The current subsidence monitoring program consists of on the ground surveys and a photogrammetrical survey of mining on East Mountain.

INSPECTION MEMO
ACT/015/017
June 30, 1982
Page 3

817.150 - .176 Roads

Maintenance work is needed on the berm along the fill side of the road to the powder and primer magazines. The berm prevents water from eroding the downslope to the main access road, below. This slope has a high potential for erosion.

Barton Kale
BARTON KALE
FIELD SPECIALIST

BK/tck

cc: Tom Ehmett, OSM
Val Payne, Emery Mining Co.
Larry Guymon, Emery Mining Co.
Inspection Staff

Statistics:

Vehicle: EX #71885 - - 426 miles
Per diem: 2 persons x 2 days, 12 hours = 164.52
Grant: A & E