

*File*



STATE OF UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

Norman H. Bangerter, Governor  
Dee C. Hansen, Executive Director  
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

Permittee and/or Operators Name: Emery Mining Company  
Business Address: P.O. Box 310, Huntington UTAH 84528  
Mine Name: Des Bee Dove Mine Permit Number: ACT 1015/617  
Type of Mining Activity: Underground  Surface  Other   
County: Emery  
Company Official(s): Val Payne  
State Official(s): Barton Kate  
Inspection Date and Time: 12-12-85 10:30 AM - 4 PM  
Partial:  Complete:  Date of Last Inspection: 11-27-85  
Weather Conditions: Clear - Sunny  
Acreage: Permitted 2850 Disturbed 47 Regraded  Seeded  Bonded 2850 47  
Enforcement Action: NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	Comments
1. PERMITS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
2. SIGNS AND MARKERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
3. TOPSOIL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
b. DIVERSION'S	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
c. SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
d. OTHER SEDIMENT CONTROL MEASURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
e. SURFACE AND GROUNDWATER MONITORING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
f. EFFLUENT LIMITATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
5. EXPLOSIVES	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
7. COAL PROCESSING WASTE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
8. NONCOAL WASTE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
10. SLIDES AND OTHER DAMAGE	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
11. CONTEMPORANEOUS RECLAMATION	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
12. BACKFILLING AND GRADING	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
13. REVEGETATION	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
14. SUBSIDENCE CONTROL	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
15. CESSATION OF OPERATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
16. ROADS				
a. CONSTRUCTION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
b. DRAINAGE CONTROLS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
d. SURFACING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
e. MAINTENANCE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
17. OTHER TRANSPORTATION FACILITIES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
18. SUPPORT FACILITIES AND UTILITY INSTALLATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

INSPECTION REPORT  
(Page 2)

Permit Number: ACT/015/017

Date of Inspection: Dec 12 1985

COMMENTS

(Comments are Numbered to Correspond with Topics Listed Above)

4/0. All ditches and culverts were functioning as designed

Copy of this Report:

Mailed to: Dan McFrittin, Larry Geyman

Given to: Joe Hellich

Inspectors Signature and Number: Burt Hale #6 Jan 13, 1986

