

NO. N 86-10-2-1

notice of violation

To the following Permittee or Operator:

Name Utah Power and Light Co
 Mine Oes-Bee-Dove Surface Underground Other
 County Emerg State Utah Telephone 687-9821
 Mailing Address P.O. Box 310 Huntington, UT 84528
 State Permit No. ACT/015/017
 Ownership Category State Federal Fee Mixed
 Date of inspection June 3, 1986, 19____
 Time of inspection 10:00 a.m. p.m. to 12:00 a.m. p.m.
 Operator Name (other than Permittee) _____
 Mailing Address _____

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining** is is not expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/ mailing 6/3/86 Time of service/ mailing 12:15 a.m. p.m.

Val Payne
 Permittee/Operator representative

Environmental Engineer
 Title

Val Payne
 Signature

Philip Ralphs
 Division of Oil, Gas & Mining representative

Field Specialist
 Title

Philip M Ralphs
 Signature

10
 Identification Number

SEE REVERSE SIDE

WHITE-DOG M YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE

1002

NOTICE OF VIOLATION NO. N _____

Violation No. 1 of 1

Nature of violation

Failure to ~~not~~ construct and maintain Class I Haul Road in order to minimize erosion and siltation, and prevent, to the extent possible, contributions of suspended solids to runoff permit area.
from

Provisions of act, regulations or permit violated

UMC 817.150 (a) and (b)
UMC 817.45 (i)

Portion of operation to which notice applies

Class I Haul Road west and south facing outslope from sediment pond to west to the road cut.

Remedial action required (including any interim steps)

Implement adequate sediment controls to reduce erosion and prevent suspended solids from running-off permit area. to the extent possible,

Abatement time (including interim steps)

June 30, 1986.