0014

File

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

Permittee and/or Operators Name: Utah Power & Light Co.
Business Address: P.O. Box 310 Huntington, UT 84528
Mine Name: Des-Bee-Dove Permit Number: ACT/015/017
Type of Mining Activity: Underground X Surface ___ Other ___
County: Emery
Company Official(s): Val Payne
State Official(s): Phil Ralphs
Inspection Date and Time: 6/3/86 10:00 am - 12:00 noon
Partial: ✓ Complete: ___ Date of Last Inspection: ___
Weather Conditions: Clear & Hot
Acreage: Permitted ___ Disturbed ___ Regraded ___ Seeded ___ Bonded ___
Enforcement Action: N86-10-2-1

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	Comments
1. PERMITS				
2. SIGNS AND MARKERS				
3. TOPSOIL				
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS				
b. DIVERSION'S				
c. SEDIMENT PONDS AND IMPOUNDMENTS				
d. OTHER SEDIMENT CONTROL MEASURES				
e. SURFACE AND GROUNDWATER MONITORING				
f. EFFLUENT LIMITATIONS				
5. EXPLOSIVES				
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL				
7. COAL PROCESSING WASTE				
8. NONCOAL WASTE				
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES				
10. SLIDES AND OTHER DAMAGE				
11. CONTEMPORANEOUS RECLAMATION				
12. BACKFILLING AND GRADING				
13. REVEGETATION				
14. SUBSIDENCE CONTROL				
15. CESSATION OF OPERATIONS				
16. ROADS				
a. CONSTRUCTION		✓		✓
b. DRAINAGE CONTROLS		✓		✓
d. SURFACING				
e. MAINTENANCE				
17. OTHER TRANSPORTATION FACILITIES				
18. SUPPORT FACILITIES AND UTILITY INSTALLATIONS				

INSPECTION REPORT
(Page 2)

Permit Number: ACT/015/017 Date of Inspection: 6/9/86

COMMENTS

(Comments are Numbered to Correspond with Topics Listed Above)

The purpose of this Inspection was to address concerns of Ten-Day Notice (TDN) X-86-2-114-4 issued by OSM Reclamation Specialist Henry Austin. Specific concern dealt with the maintenance of the Des-Bee-Dove Class I Haul Road. As a result of this Inspection NOV N86-10-2-1 was issued for "Failure to construct and maintain a Class I Haul to prevent, to the extent possible, erosion and siltation." The Abatement measures for the NOV include ~~#~~ "Implement adequate sediment controls to reduce erosion and prevent, to the extent possible, suspended solids from running off permit area."

Copy of this Report:
Mailed to: Donna Griffin (OSM), Val Payne (UP&L)
Given to: Joe Helfrich, John Whitehead

Inspectors Signature and Number: P. Philip M Rafka, #10, 6/9/86

0365Q 1-2

Inspection Report
(continuation sheet)

Page ____ of ____

Permit Number: _____

Date of Inspection: _____

COMMENTS

Inspectors Signature, Number and Date: _____

0365Q 3