

0009



STATE OF UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

*pg 23-81*

*file*

*ph 2/2/87*  
*ju 2/2/87*

Norman H. Bangertter, Governor  
Dee C. Hansen, Executive Director  
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

**INSPECTION REPORT**

Permittee and/or Operators Name: Utah Power & Light / Mining Division  
Business Address: P.O. Box 310 Huntington, Utah 84528  
Mine Name: Des-Bee-Dove Permit Number: ACT/015/017  
Type of Mining Activity: Underground  Surface  Other   
County: Emery  
Company Official (s): Val Payne  
State Official(s): Phil Ralphs & Pam Grubaugh-Littig  
Inspection Date & Time: January 15, 1987 @ 12:00 N  
Partial:  Complete:  Date of Last Inspection: 12/11/86  
Weather Conditions: Cloudy & Cool  
Acreage: Permitted 2847 Disturbed 74.5 Regraded        Seeded        Bonded 74.5  
Enforcement Action: None

**COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS**

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	( X )	( )	( )	( )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	( X )	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( X )	( )	( )	( X )
d. OTHER SEDIMENT CONTROL MEASURES	( X )	( )	( )	( X )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( X )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( X )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( X )	( )	( )	( X )

INSPECTION REPORT  
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/017

DATE OF INSPECTION: 01/15/87

(Comments are Numbered to Correspond with Topics Listed Above)

4.c) SEDIMENT PONDS & IMPOUNDMENTS:

The Operator has completed the cleaning of the sediment pond. The pond is mostly dry at the present time. The sediment was hauled to the Wilberg Waste Rock Disposal area and placed in disposal cell #6 where it is currently being allowed to dry before eventual reclamation of the disposal cell

The Operator has placed concrete around the base of the stand pipe which serves as the principal spillway of the sediment pond. This was done to add to the stability of the stand pipe. The function and design of the spillway were not altered by the concrete, and therefore, this action was not considered a modification, which would have required prior Division approval.

The Operator has completed construction of a wire fence around the sediment pond. This was a requirement of Utah State Lands, whom are surface owners of the sediment pond area.

4.d) OTHER SEDIMENT CONTROL MEASURES:

The sediment traps which are located along the sediment pond access road were cleaned at the same time the sediment pond was cleaned. This maintenance was noted as needing to be done in the previous inspection Report. Following cleaning the Operator replaced the silt fence material with "Typar" fabric and wire mesh backing.

18.) SUPPORT FACILITIES AND UTILITY INSTALLATIONS:

The Operator is in the process of installing a water storage tank at the mine site. Mr. Payne was told that the surface facilities map for the site would need to be updated to show the tank.

Copy of this Report:

Mailed to: Donna Griffin (OSM) & Val Payne (UP&L)

Given to: Joe Helfrich, John Whitehead, and Pam Grubaugh-Littig

Inspectors Signature and Number: Philip M. Raphs, #10, 1/30/87