0015

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

File

inspection report

Permit No. ACT/015/017

Inspection Date April 6 & 7, 1988

Permittee/Operator Name Utah Power & Light Company

Business Address P.O. Box 310

City Huntington State Ut Zip 84528

Mine Des-Bee-Dove ☐ Surface ☒ Underground ☐ Other

County Emery State UT

Company Official(s) Val Payne and Ray Christensen

State Official(s) Harold G. Sandbeck

Time of inspection April 6 8:00 x 8:00 ☒ a.m. ☐ p.m. to 11:00 x 1:00 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete
April 7 →

Date of last inspection January 21, 1988 Weather conditions Clear & Warm

Acreage 2847 ☒ Permitted 74.5 ☒ Disturbed ☐ Regraded ☐ Seeded 74.5 ☒ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
a – Stream channel diversions	☒	☐	☐	☐
b – Diversions	☒	☐	☐	☒
c – Sediment ponds and impoundments	☒	☐	☐	☒
d – Other sediment control measures	☒	☐	☐	☒
e – Surface and groundwater monitoring	☒	☐	☐	☐
f – Effluent limitations	☒	☐	☐	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☒	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☒
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☐	☐	☒	☐
11. Contemporaneous reclamation	☐	☐	☒	☐
12. Backfilling and grading	☐	☐	☒	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☒	☐	☐	☐
15. Cessation of operations	☒	☐	☐	☐
16. Roads				
– Construction	☒	☐	☐	☐
– Drainage controls	☒	☐	☐	☐
– Surfacing	☒	☐	☐	☐
– Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☒	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/017

Inspection Date April 6 & 7, 1988

Please number comments to correspond with topics on previous page.

General Comments: Val Payne (UP&L) and Ray Christensen (UP&L) accompanied the undersigned inspector on this complete inspection. On April 6, 1988, the permit and associated documents were inspected. On April 7, 1988, a mid-term review was conducted in concert with the complete inspection. DOGM review members consisted of John Whitehead (Permit Supervisor), Tom Munson (Hydrologist), Dan Duce (Soils Spec.), Brent Stettler (Biologist) and Pam Grubaugh-Littig (Engineer). Ground conditions were dry with no snow cover.

1.) Permits: Des Bee Dove mine received a new NPDES (UPDES) permit on February 11, 1988. The Utah Bureau of Water Pollution Control issued the permit which expires on October 31, 1992.

4.b.) Diversions: A half-round culvert located on the eastern edge of the steep fill slope below the tipple pad is developing erosion gullies from drainage undercutting the sides of the culvert. This culvert carries disturbed area drainage to the sediment pond. A redesign of this drainage is required to prevent the undercutting of the half-round culvert. The operator will submit redesign plans on or before June 10, 1988.

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/017

Inspection Date April 6 & 7, 1988

Please number comments to correspond with topics on previous page.

4.c.) Sediment Ponds and Impoundments: The pond inspection for the 1st quarter of 1988 was in order. The operator was informed that the northern pond embankment requires minor repair work.

4.d.) Other Sediment Control Measures: Two siltfences near the pond area require cleaning. Currently, the siltfences are functional and able to hold more sediment.

7.) Coal Processing Waste: The Waste Rock Disposal Site report for the 4th quarter of 1987 was in order.

Copy of report mailed to Val Payne, UP&L and Brian Smith, OSM

Copy of report given to Joe Helfrich, DOGM

Inspector's signature Harold G. Sandell 11 April 88 No. 27

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE