0011

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/015/017
Inspection Date 10/1/91

Permittee/Operator Name PacifiCorp Electric Operations
Business Address 210 S. Main, Suite 2100
City Salt Lake City State Ut. Zip 84140-0021
Mine Des Bee Dove ☐ Surface ☒ Underground ☐ Other
County Emery State Ut
Company Official(s) Guy Davis & Del Grange
State Official(s) Bill Malencek
Time of inspection 8:00 ☐ a.m. ☐ p.m. to 4:00 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete
Date of last inspection 8/28/91 Weather conditions Clear/Warm - 70's
Acreage 2847 ☐ Permitted 78 ☐ Disturbed ☐ Regraded ☐ Seeded 78 ☐ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☒	☐
— Diversions	☒	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☐
— Other sediment control measures	☒	☐	☐	☐
— Surface and groundwater monitoring	☒	☐	☐	☐
— Effluent limitations	☒	☐	☐	☐
5. Explosives	☒	☐	☐	☐
6. Development waste and spoil disposal	☒	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☒	☐	☐	☐
11. Contemporaneous reclamation	☒	☐	☐	☐
12. Backfilling and grading	☒	☐	☐	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☒	☐	☐	☐
15. Cessation of operations	☒	☐	☐	☐
16. Roads				
— Construction	☒	☐	☐	☐
— Drainage controls	☒	☐	☐	☐
— Surfacing	☒	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☒	☐	☐	☐
18. Support facilities and utility installations	☒	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

INSPECTION REPORT COMMENTS

Permit No. ACT/015/017

Inspection Date 10/1/91

Please number comments to correspond with topics on previous page.

General Comments: On the fourpart of October (10-5/9-91) the general area including the Des Bee Dove mine site received high intensity storms. The permittee repaired ditches immediately after the storm, but the evidence of overflow on the road in the tipple area was still visible

RECORDS: A complete records review was conducted with highlights noted herein. The records were in good form and were readily available. The permittee has a good record system for DOGM generated paperwork.

Permit - Renewed and approved 5/31/91

Permit Stipulations - Time of record. Information has been provided to the Division. Some confusion still exists on certified impoundment reports (R-614-301-514.312) ie., the question what impoundment reports need to be certified by a registered engineer?

(a) The annual report + the construction report

(b) The Quarterly report

The permittee and the undersigned interpret the regulations and believe (a) needs to be certified by a PE, but (b) above need not. This condition and/or stipulation needs a followup to set the record straight.

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/017

Inspection Date 10/1/91

Please number comments to correspond with topics on previous page.

Insurance - Assoc. Electric & Gas Insurance Service, Inc, $35 million, period 2/24/91 - 2/24/92. New format submitted to the Division on 6/28/91

Bond. American Casualty Co, corporate surety bond for $1,837,712.

Sed Pond.

Quarterly Inspection 3/19, 6/26, & 9/20/91
Annual Report On Record

Waste Rock

Quarterly Inspection 4/9, 6/21, and 3rd quarter report field work complete but report in the process of being finalized

AVS. a AVS check was made and no problems noted.

UPDES

- Monthly reports prepared and distributed to required agencies quarterly. The second quarter report was sent on 8/30/91. Third quarter report is now being assembled.
- Pond discharges. Pond is being decanted in preparation for cleaning. Samples were taken on 8/30/91 and 9/6/91. The lab results show the water quality on the 9/6 samples is better on some key parameters than the 8/30/91 sample.

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

INSPECTION REPORT COMMENTS

Permit No. ACT/015/017

Inspection Date 10/1/91

Please number comments to correspond with topics on previous page.

Water Monitoring. Records were reviewed and found to be in order, including submitting information. Other records including certified maps, designs, and subsidence reports were on file.

Field. The permittee has performed work outline in the inspection report of 8/28/91 as follows:

- Cleaned culvert adjacent to the tipple
- Station inlet 142 on the haul road was cleaned
- Water bar by the bath house was cleaned.
- Berms were maintained by the Beehive portals.

Additional maintenance work was identified that had been brough on by a recent storm which included:

- Road from slide to the upper portals needs additional work to prevent uncontrolled runoff from going down the road.
- Permittee needs to reevaluate the slide and determine if the adjacent escarpment area is stable enough to permit blasting and slide rock removal
- Keep an eye on the culvert adjacent to the tipple.

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. Ac7/015/017

Inspection Date 10/1/91

Please number comments to correspond with topics on previous page.

- Clean ditch adjacent to and below the fuel tanks.
- Remove rocks from the Shop/Office pad area.

None of the items noted herein are violations relating to performance standards. However, suggestions made herein are of a preventative nature in order to avoid the above environmental from getting out of compliance should another storm hit the mine site

Copy of report mailed to PEO/Blake Webster; OSM/Brain Smith; DOGM/Joe Helfrich

Copy of report ~~given to~~ filed RFO

Inspector's signature [signature] No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

10/2/91

DOGM/IR-2 an equal opportunity employer 11/86 001049

cc: Guy Davis