


One Utah Center
201 South Main, Suite 2100
Salt Lake City, Utah 84140-0021
(801) 220-2000



April 14, 1995

Utah Coal Regulatory Program
Division of Oil, Gas and Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

Attention: Pamela Grubaugh-Littig

RE: ANNUAL REPORTS FOR 1994, PACIFICORP, DES BEE DOVE MINES, #6
ACT/015/017, DEER CREEK MINE, ACT/015/018, #6
COTTONWOOD/WILBERG MINE, ACT/015/019, TRAIL MOUNTAIN MINE,
#6 ACT/015/009, EMERY COUNTY, UTAH. #6

Transmitted herewith, please find one (1) copy of the Annual Reports for the above referenced PacifiCorp operations. The materials are organized as in previous years.

If you have questions regarding this information, please call me at 653-2312 ext. 16.

Sincerely,

Val Payne
Sr. Environmental Engineer

/vp
Enclosure

cc: M. Moon
B. Webster
File

Post-It™ brand fax transmittal memo 7671		# of pages	1
To	BLANG	From	VAL
Co.		Co.	
Dept.		Phone #	
Fax #		Fax #	

One Utah Center
201 South Main, Suite 2100
Salt Lake City, Utah 84140-0021
(801) 220-2000



April 14, 1995

Utah Coal Regulatory Program
Division of Oil, Gas and Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

Attention: Pamela Grubaugh-Littig

RE: ANNUAL REPORTS FOR 1994, PACIFICORP, DES BEE DOVE MINES,
ACT/015/017, DEER CREEK MINE, ACT/015/018,
COTTONWOOD/WILBERG MINE, ACT/015/019, TRAIL MOUNTAIN MINE,
ACT/015/009, EMERY COUNTY, UTAH.

Transmitted herewith, please find one (1) copy of the Annual Reports for the above referenced PacificCorp operations. The materials are organized as in previous years.

If you have questions regarding this information, please call me at 653-2312 ext. 16.

Sincerely,

A handwritten signature in cursive script that reads "Val Payne".

Val Payne
Sr. Environmental Engineer

/vp
Enclosure

cc: M. Moon
B. Webster
File

COTTONWOOD/WILBERG/DES BEE DOVE
ACT/015/019 AND ACT/015/017
4th QUARTER 1995

#6 #6
Copy to #6
ACT/015/019

INTRODUCTION

The original Waste Rock Disposal Site is located on a 16 acre right-of-way from the BLM located approximately two miles from the Cottonwood/Wilberg mine site along the east side of State Road 57.

Top-soil and sub-soil had been placed on the north end of the original site.

A new disposal site was constructed during the spring and summer of 1990 on an approved right-of-way from the BLM located west of State Road 57 and 1.75 miles south of the Cottonwood/Wilberg mine site. This facility is designed for 784,000 cubic yards of material and is planned to last for the life of the mines which it serves.

OPERATION

Fourth quarter pond cleaning sediment had been placed in its designated cell on active site.

INSPECTION

The new waste storage site was inspected on November 29, 1995 for structural stability. Inspection of the operation of this facility is conducted on a continual basis. At the time of inspection, refuse covered approximately 40% of the active site.


This area does not show any signs of instability or weakness. The small seep at the sediment pond area still could not be observed due to water elevation of the pond. Water seepage was occurring in the ditch leading to the pond.

No new rills or sluffing were observed during this inspection.

The sediment pond and dam at the new site were inspected. No signs of instability or weakness were found. The discharge structure and emergency spillway were intact and operational according to design.

CERTIFICATION

I do hereby certify that the Cottonwood/Wilberg/Des Bee Dove Waste Rock Sites are constructed according to sound engineering practices, and I do also certify that there was no evidence of significant instability, structural weakness, or other hazardous conditions at the time of this inspection.


John Christensen
P.E. #165651

**COTTONWOOD/WILBERG/DES BEE DOVE
ACT/015/019 AND ACT/015/017
3rd QUARTER 1995**

ACT/015/015 #6

Copy to

ACT/015/017 #6

INTRODUCTION

The original Waste Rock Disposal Site is located on a 16 acre right-of-way from the BLM located approximately two miles from the Cottonwood/Wilberg mine site along the east side of State Road 57.

Top-soil and sub-soil had been placed on the north end of the original site. Final slope grading and seeding will be completed by years end.

A new disposal site was constructed during the spring and summer of 1990 on an approved right-of-way from the BLM located west of State Road 57 and 1.75 miles south of the Cottonwood/Wilberg mine site. This facility is designed for 784,000 cubic yards of material and is planned to last for the life of the mines which it serves.

OPERATION

First quarter pond cleaning sediment had been removed from its designated cell and placed on active site. Cell had been prepared for Fall pond cleaning. A new berm was established for the next series of lifts.

INSPECTION

The new waste storage site was inspected on September 26, 1995 for structural stability. Inspection of the operation of this facility is conducted on a continual basis. At the time of inspection, refuse covered approximately 10% of the active site.

This area does not show any signs of instability or weakness. The small seep at the sediment pond area still could not be observed due to water elevation of the pond. Water seepage was occurring in the ditch leading to the pond.

No new rills or sluffing were observed during this inspection.

The sediment pond and dam at the new site were inspected. No signs of instability or weakness were found. The discharge structure and emergency spillway were intact and operational according to design.

CERTIFICATION

I do hereby certify that the Cottonwood/Wilberg/Des Bee Dove Waste Rock Sites are constructed according to sound engineering practices, and I do also certify that there was no evidence of significant instability, structural weakness, or other hazardous conditions at the time of this inspection.

John Christensen
John Christensen
P.E. #165651



File - ACT/015/017 #6

COTTONWOOD/WILBERG/DES BEE DOVE
ACT/015/019 AND ACT/015/017
2nd QUARTER 1995

Copy do
ACT/015/019 #6

INTRODUCTION

The original Waste Rock Disposal Site is located on a 16 acre right-of-way from the BLM located approximately two miles from the Cottonwood/Wilberg mine site along the east side of State Road 57.

A new disposal site was constructed during the spring and summer of 1990 on an approved right-of-way from the BLM located west of State Road 57 and 1.75 miles south of the Cottonwood/Wilberg mine site. This facility is designed for 784,000 cubic yards of material and is planned to last for the life of the mines which it serves.

OPERATION

First quarter pond cleaning sediment was contained in the designated cell in the north end of the site. Pond cleaning sediment drying in the cell. New material was placed on the outslope toward the pond to establish a new berm for the next lift.

INSPECTION

The new waste storage site was inspected on June 29, 1995 for structural stability. Inspection of the operation of this facility is conducted on a continual basis. At the time of inspection, refuse covered approximately 20% of the active site.

This area does not show any signs of instability or weakness. The small seep at the sediment pond area could not be observed due to water elevation of the pond.

No new rills or sluffing were observed during this inspection.

The sediment pond and dam at the new site were inspected. No signs of instability or weakness were found. The discharge structure and emergency spillway were intact and operational according to design.

CERTIFICATION

I do hereby certify that the Cottonwood/Wilberg/Des Bee Dove Waste Rock Sites are constructed according to sound engineering practices, and I do also certify that there was no evidence of significant instability, structural weakness, or other hazardous conditions at the time of this inspection.



John Christensen
P.E. #165651