

INSPECTION REPORT

Partial Complete Exploration
 Inspection Date: 06/11/2003/ Time: 12:50 PM to 3:21 PM
 Inspection Date: 06/27/2003/ Time: 9:06 AM to 12:30 PM
 Date of Last Inspection: 05/22/2003

Mine Name: Des Bee Dove Mine County: Emery Permit Number: C/015/017
 Permittee and/or Operator's Name: PacifiCorp
 Business Address: P.O. Box 310, Huntington, Utah 84528
 Company Official(s): Dennis Oakley
 State Official(s): Jim Smith, Jerriann Ernsten Federal Official(s): None
 Weather Conditions: Clear, warm, sunny
 Type of Mining Activity: Underground Surface Prep Plant Other
 Existing Acreage: Permitted 2760 Disturbed 24 Regraded Seeded
 Status: Active XXX

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL ISSUES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS CHECK (4 th Quarter- April, May, June)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT
(Continuation Sheet)

PERMIT NUMBER: C/015/017

DATE OF INSPECTION: 06/11,27/2003

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The March 28, 2003 sedimentation pond inspection report was checked: 0.05 acre-feet of storage remains. The pond has been decanted recently. The inspection report for the current quarter will be checked next month.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

The only remaining ASCA - straw bales at the sub-soil pile - was functioning. The depression upstream of the bales still held water from recent rains.

4E. HYDROLOGIC BALANCE: EFFLUENT LIMITATIONS

UPDES permit was renewed, effective May 1, 2003. The pond has been decanted recently, and analysis results should be on the DMR, which will be submitted next month.

8. NONCOAL WASTE

The pile of waste gathered from along the cattle trail has been removed.

12. BACKFILLING AND GRADING

Backfilling and grading at the mine-site has been completed.

13. REVEGETATION

As of the June 27 inspection, revegetation at the mine-site has been completed. Palmer penstemon was in bloom at the water-tank site. Squirrel-tail and other grasses (Indian ricegrass?) are growing in the Phase-1 area, but distribution is uneven.

16A. ROADS: CONSTRUCTION/MAINTENANCE/SURFACING

The road to the sedimentation pond is the only remaining road.

INSPECTION REPORT
(Continuation Sheet)

PERMIT NUMBER: C/015/017

DATE OF INSPECTION: 06/11,27/2003

19. AVS CHECK

An AVS check was done on April 16, 2003. There were no violations retrieved by the system.

21. BONDING AND INSURANCE

The insurance policy is effective April 1, 2003 to April 1, 2004. The policy is with Associated Electric and Gas Insurance Services, Ltd., Hamilton, Bermuda. General liability is for \$2 million and excess liability is for \$20 million. The Division is named as the certificate holder, and the Division will be given 45 days advance notice of policy cancellation.

Inspector's Signature: _____ Date: July 1, 2003
James D. Smith # 43

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM
Chuck Semborski, PacifiCorp, via email
Price Field office

O:\015017.DBD\Compliance\2003\c_0627.doc