



State of Utah

Department of
Environmental Quality

Dianne R. Nielson, Ph.D.
Executive Director

DIVISION OF WATER QUALITY
Walter L. Baker, P.E.
Director

JON M. HUNTSMAN, JR.
Governor

GARY HERBERT
Lieutenant Governor

March 9, 2006

Mr. Dennis Oakley
Energy West Mining Company
P.O. Box 310
Huntington, Utah 84528

Subject: Site Visits & Inspections – Hunter Coal Facility, Deer Creek,
Cottonwood/Wilberg, Des-Bee-Dove & Trail Mountain Mines.

Dear Mr. Oakley:

On March 7, 2006 I met with you to conduct both reconnaissance and storm water inspections in regards to the above referenced facilities and UPDES Permit Nos. UTG04009, UT0023604, UT0022896, UTG040022, and UT0023728, respectively.

Enclosed are copies of the inspection reports for your records. I appreciated your time and efforts to facilitate the inspections. If you have any questions, please contact me at (801) 538-6779 or by e-mail at jstudenka@utah.gov.

Sincerely,

Jeff Studenka, Environmental Scientist
Permits & Compliance Section

Enclosures

cc (w/encl): Darcy O'connor, EPA Region VIII
Claron Bjork, SE District Health Department
Dave Ariotti, SE District Engineer
Pam Grubaugh-Littig, Division of Oil Gas & Mines
Tom Rushing, DWQ (Storm water reports only)

F:\wp\PacifiCorp\Followup2006.ltr.doc

RECEIVED
MAR 14 2006

NPDES Compliance Inspection Report

Form Approved
OMB No. 2040-0003
Approval Expires 7-31-85

Section A: National Data System Coding

Transaction Code	NPDES	Yr/Mo/Day	Inspection Type	Inspector	Fac Type
1 [N]	2 []	3 [UTIGI040022]	11 12 [06 03 07]	17 18 [W]	19 [S]
Remarks					66
21 []	Reserved	Facility Evaluation Rating	BI	QA	Reserved
67 []	70 [S]	71 [N]	72 [N]	73 []	75 []

Section B: Facility Data

Name and Location of Facility Inspected		Entry Time	Permit Effective Date
PacifiCorp - Energy West - Des-Bee-Dove Mine Reclamation Site 8-Miles West off Hwy. 29 Orangeville, Utah		9:45 am	11/1/2002
		Exit Time/Date	Permit Expiration Date
		1:30 pm/3-7-06	10/31/2007
Name(s) of On-Site Representative(s)		Title(s)	Phone No(s)
Mr. Dennis Oakley P.O. Box 310 Huntington, UT 84528		Environmental Engineer	435-687-4825
Name, Address of Responsible Official		Title	
Same as above			
		Phone No.	Contacted
			Yes

Section C: Areas Evaluated During Inspection

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

Permit	Flow Measurement	Pretreatment	Operations & Maintenance
Records/Reports	Laboratory	Compliance Schedules	Sludge Disposal
Facility Site Review	Effluent/Receiving Water	Self-Monitoring Program	S Other: Storm Water

Section D: Summary of Findings/Comments (Attach additional sheets if necessary)

The facility had a Stormwater Pollution Prevention Plan in place since 1998, including the certification by Mr. John Christensen, P.E., and it was recently updated in September 2005 and finally on January 31, 2006. Mr. Oakley indicated that the plan was updated to reflect the mine's inactive and completely reclaimed status, respectively. The sediment pond and final outfall have been removed and the area fully reclaimed. There is no longer a potential to discharge from this facility. Mr. Oakley was very accommodating throughout the inspection, which included a file review followed by a tour of the reclaimed mine site area. There were no deficiencies observed. This site is now "inactive", therefore DMRs will no longer need to be submitted, the SWPPP for this facility will no longer need to be maintained and no further site inspections will be necessary.

Name(s) and Signature(s) of Inspector(s)	Agency/Office/Telephone	Date
Jeff Studenka, Environmental Scientist <i>Jeff Studenka</i>	(801) 538-6779 DIVISION OF WATER QUALITY	3-8-06
N/A	Agency/Office/Telephone	Date
N/A	Agency/Office	Date

Regulatory Office Use Only

Action Taken	Date	Compliance Status
		Noncompliance Compliance

RECEIVED

MAR 14 2006

DIV. OF OIL, GAS & MINING

