

0011

**From:** Steve Demczak  
**To:** Angela Nance; Oakley, Dennis  
**Date:** 5/5/2009 1:56 PM  
**Subject:** April Insp  
**Attachments:** 20090505140841.pdf

*Outgoing*  
*4/8/15/0017*

*ⓧ*



State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

Table with 2 columns: Company, Name, Title. Row 1: Dennis Oakley, Environmental Engineer. Row 2: Steve Demczak, Environmental Scientist III.

Inspection Report

Table with 2 columns: Field, Value. Fields include Permit Number, Inspection Type, Inspection Date, Start Date/Time, End Date/Time, Last Inspection.

Inspector: Steve Demczak, Environmental Scientist III

Weather: Sunny, 60's

InspectionID Report Number: 1976

Accepted by: jhelfric
5/5/2009

Permitee: PACIFICORP
Operator: ENERGY WEST MINING CO
Site: DES BEE DOVE MINE
Address: PO BOX 310, HUNTINGTON UT 84528
County: EMERY
Permit Type: PERMANENT COAL PROGRAM
Permit Status: RECLAIMED

Current Acreages

Table with 2 columns: Value, Description. Rows: 134.31 Total Permitted, 36.02 Total Disturbed, Phase I, Phase II, Phase III.

Mineral Ownership

- Checked: Federal, Fee
Unchecked: State, County, Other

Types of Operations

- Checked: Underground
Unchecked: Surface, Loadout, Processing, Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violations were written or pending.

Inspector's Signature: [Signature]
Steve Demczak, Environmental Scientist III

Date: Monday, April 20, 2009

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

**REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS**

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

**2. Signs and Markers**

Identification signs was located on the trail to the mine.

**3. Topsoil**

All topsoil was used in Reclamation.

**4.a Hydrologic Balance: Diversions**

The diversions were functioning as designed. There were no signs of erosion.

**4.c Hydrologic Balance: Other Sediment Control Measures**

The disturb area is pocked for sediment control.

**7. Coal Mine Waste, Refuse Piles, Impoundments**

There are no coal mine waste piles at this site.

**8. Noncoal Waste**

The reclaim area was clear of non-coal waste material.

**9. Protection of Fish, Wildlife and Related Environmental Issues**

Wildlife has been grazing on the site.

**10. Slides and Other Damage**

No slides were noticed during the inspection.

**12. Backfilling And Grading**

The site was backfilled and graded.

**13. Revegetation**

It is to early in the season for new vegetation to come up from the ground.

**15. Cessation of Operations**

The mine is completely reclaimed.

**22. Other**

The permittee will fixing a couple of erosion rills through the trail area.