

0020

From: Steve Demczak
To: Angela Nance; Oakley, Dennis
Date: 12/7/2009 11:07 AM
Subject: Nov Insp. Report
Attachments: 20091207112238.pdf

Outgoing
00150017
R



State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

Representatives Present During the Inspection:

| | | |
|---------|---------------|-----------------------------|
| Company | Dennis Oakley | Environmental Engineer |
| OGM | Steve Demczak | Environmental Scientist III |

Inspection Report

| | |
|------------------|----------------------------|
| Permit Number: | C0150017 |
| Inspection Type: | COMPLETE |
| Inspection Date: | Tuesday, November 17, 2009 |
| Start Date/Time: | 11/17/2009 10:00:00 AM |
| End Date/Time: | 11/17/2009 1:00:00 PM |
| Last Inspection: | Monday, October 12, 2009 |

Inspector: Steve Demczak, Environmental Scientist III

Weather: Sunny 30's

InspectionID Report Number: 2201

Accepted by: jhelfric
12/7/2009

Permitee: PACIFICORP
 Operator: ENERGY WEST MINING CO
 Site: DES BEE DOVE MINE
 Address: PO BOX 310, HUNTINGTON UT 84528
 County: EMERY
 Permit Type: PERMANENT COAL PROGRAM
 Permit Status: RECLAIMED

Current Acreages

| | |
|--------|-----------------|
| 134.31 | Total Permitted |
| 36.02 | Total Disturbed |
| 43.40 | Phase I |
| | Phase II |
| 2.52 | Phase III |

Mineral Ownership

- Federal
- State
- County
- Fee
- Other


Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violations were issued

Inspector's Signature:


 Steve Demczak, Environmental Scientist III
 Inspector ID Number: 39

Date Thursday, November 19, 2009

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
 telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

| | Evaluated | Not Applicable | Comment | Enforcement |
|--|-------------------------------------|-------------------------------------|-------------------------------------|--------------------------|
| 1. Permits, Change, Transfer, Renewal, Sale | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. Signs and Markers | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Topsoil | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 4.a Hydrologic Balance: Diversions | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 4.b Hydrologic Balance: Sediment Ponds and Impoundments | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 4.c Hydrologic Balance: Other Sediment Control Measures | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 4.d Hydrologic Balance: Water Monitoring | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 4.e Hydrologic Balance: Effluent Limitations | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 5. Explosives | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 6. Disposal of Excess Spoil, Fills, Benches | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 7. Coal Mine Waste, Refuse Piles, Impoundments | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 8. Noncoal Waste | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 9. Protection of Fish, Wildlife and Related Environmental Issues | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 10. Slides and Other Damage | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 11. Contemporaneous Reclamation | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 12. Backfilling And Grading | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 13. Revegetation | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 14. Subsidence Control | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 15. Cessation of Operations | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 16.a Roads: Construction, Maintenance, Surfacing | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 16.b Roads: Drainage Controls | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 17. Other Transportation Facilities | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 18. Support Facilities, Utility Installations | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 19. AVS Check | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 20. Air Quality Permit | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 21. Bonding and Insurance | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 22. Other | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

1. Permits, Change, Transfer, Renewal, Sale

The DOGM permit will expire on Aug.30, 2010.

2. Signs and Markers

The identification sign is located on the trail to the property. Information contained the information required in the R645 Coal Rules.

3. Topsoil

All topsoil was used in reclamation. There were no signs of erosion on the reclaimed lands.

4.a Hydrologic Balance: Diversions

Several diversions were spot-checked with no signs of water erosion.

4.c Hydrologic Balance: Other Sediment Control Measures

The entire site is pocked to prevent sediment from leaving the reclaim area.

6. Disposal of Excess Spoil, Fills, Benches

Portals have been backfilled.

8. Noncoal Waste

The mine site was clear of non-coal waste materials.

10. Slides and Other Damage

No slides or damage was noticed during the inspection.

12. Backfilling And Grading

The mine site is completely backfilled and graded.

13. Revegetation

The mine site has been seeded and vegetation is growing on the site.

18. Support Facilities, Utility Installations

There are no facilities.

21. Bonding and Insurance

The insurance will expire on Aug. 28, 2010. The company affording coverage is ASSOC. Electric & Gas Ins Serv LTD. The bond amount is \$1,169,718. The reclamation agreement was inspected and was signed by both parties.