State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

GARY R. HERBERT
Governor

GREG BELL
Lieutenant Governor

Inspection Report

Permit Number:	**C0150017**
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, May 08, 2012
Start Date/Time:	5/8/2012 10:00:00 AM
End Date/Time:	5/8/2012 1:00:00 PM
Last Inspection:	Thursday, April 26, 2012

Representatives Present During the Inspection:
OGM Steve Demczak

Inspector: Steve Demczak,

Weather: Sunny, 60's

InspectionID Report Number: 3097

Accepted by: jhelfric
5/15/2012

Permitee: **ENERGY WEST MINING CO**
Operator: **ENERGY WEST MINING CO**
Site: **DES BEE DOVE MINE**
Address: **PO BOX 310, HUNTINGTON UT 84528**
County: **EMERY**
Permit Type: **PERMANENT COAL PROGRAM**
Permit Status: **RECLAIMED**

Current Acreages

133.90	**Total Permitted**
40.90	**Total Disturbed**
136.58	**Phase I**
95.70	**Phase II**
95.70	**Phase III**

Mineral Ownership

- [x] Federal
- [ ] State
- [ ] County
- [x] Fee
- [ ] Other

Types of Operations

- [x] Underground
- [ ] Surface
- [ ] Loadout
- [ ] Processing
- [ ] Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violation were issued.

Inspector's Signature:

Steve Demczak,
Inspector ID Number: 39

Date Wednesday, May 08, 2012

Note: This inspection report does not constitute an official, or compliance, with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • *www.ogm.utah.gov*

UTAH DNR OIL, GAS & MINING

Permit Number: C0150017
Inspection Type: PARTIAL
Inspection Date: Tuesday, May 08, 2012

Inspection Continuation Sheet

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	☑	☐	☑	☐
2. Signs and Markers	☑	☐	☑	☐
3. Topsoil	☑	☐	☑	☐
4.a Hydrologic Balance: Diversions	☑	☐	☑	☐
4.b Hydrologic Balance: Sediment Ponds and Impoundments	☐	☑	☐	☐
4.c Hydrologic Balance: Other Sediment Control Measures	☑	☐	☑	☐
4.d Hydrologic Balance: Water Monitoring	☐	☐	☐	☐
4.e Hydrologic Balance: Effluent Limitations	☐	☑	☐	☐
5. Explosives	☐	☑	☐	☐
6. Disposal of Excess Spoil, Fills, Benches	☐	☑	☐	☐
7. Coal Mine Waste, Refuse Piles, Impoundments	☐	☑	☐	☐
8. Noncoal Waste	☑	☐	☑	☐
9. Protection of Fish, Wildlife and Related Environmental Issues	☑	☐	☐	☐
10. Slides and Other Damage	☑	☐	☑	☐
11. Contemporaneous Reclamation	☑	☐	☐	☐
12. Backfilling And Grading	☑	☐	☑	☐
13. Revegetation	☑	☐	☑	☐
14. Subsidence Control	☐	☑	☐	☐
15. Cessation of Operations	☐	☑	☐	☐
16.a Roads: Construction, Maintenance, Surfacing	☐	☑	☐	☐
16.b Roads: Drainage Controls	☐	☑	☐	☐
17. Other Transportation Facilities	☐	☑	☐	☐
18. Support Facilities, Utility Installations	☐	☑	☐	☐
19. AVS Check	☑	☐	☑	☐
20. Air Quality Permit	☐	☑	☐	☐
21. Bonding and Insurance	☑	☐	☑	☐
22. Other	☐	☐	☐	☐

1. Permits, Change, Transfer, Renewal, Sale

No violations were issued.

2. Signs and Markers

The identification signs is located on the trail to the mine site.

3. Topsoil

All topsoil was used in reclamation.

4.a Hydrologic Balance: Diversions

The diversions are opened and functioning as designed.

4.c Hydrologic Balance: Other Sediment Control Measures

The mine site is pocked to control sediment control. No signs of sediment going offf site.

8. Noncoal Waste

The site was clear of non-coal waste materials.

10. Slides and Other Damage

No slides or other damage was noticed during the inspection.

12. Backfilling And Grading

The site is backfilled and graded to AOC standards in my opinion.

13. Revegetation

Vegetation is starting to grow again.

19. AVS Check

AVS checks are done in Salt Lake City.

21. Bonding and Insurance

The insurance will expire on Aug. 28, 2012. The company affording coverage is ASSOC. Electric & Gas Ins Serv LTD. The bond amount is $511,000. The reclamation agreement was inspected and was signed by both parties.