

0013

April 12, 1985

TO: Coal File, Enforcement and Inspection Folder
FROM: Sandy Pruitt, Mining Field Specialist *SP*
RE: Deer Creek Mine, Utah Power & Light Company, ACT/015/018, #2,
#7, Emery County, Utah

A small pre-Act mine opening has become exposed by sloughage off the cliff along the Deer Creek Mine yard. The doghole is located near the trash bin next to the warehouse/shop building. The approximate location is indicated on both attachments.

Down canyon from the mine, there is an old mine development on the west side of the canyon, evident from the road by scattered timbers and a spoil pile. This pre-Act development is not indicated on the "existing mine workings" map submitted in the Deer Creek Mine permit application. I've circled the approximate location of this development, also, Area B.

eh

Attachment

cc: Mary Ann Wright, DOGM
Pam Grubaugh-Littig, DOGM

0171Q-35

Approximate location of bogholes

USE PERMIT

ROCK DUST TANK

TRASH BIN

OIL STORAGE SHED

4000 GALLON DIESEL (STORAGE TANK (UNDERGROUND))

MAIN SUBSTATION

MATERIAL STORAGE AREA

AIR INTAKE PORTALS

WAREHOUSE & SHOP

WAREHOUSE

MATERIAL STORAGE AREA

PARKING LOT

PARKING LOT

OFFICE

BATH HOUSE

PARKING LOT

MINE CONVEYOR

AUXILIARY FAN

SE 1
4



