RE 5-4-87 0024 File

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/015/018
Inspection Date 4/15/87

Permittee/Operator Name Utah Power & Light/Mining Division
Business Address P.O. Box 310
City Huntington State Utah Zip 84523
Mine Deer Creek ☐ Surface ☒ Underground ☐ Other
County Emery State Utah
Company Official(s) Val Payne
State Official(s) Wm. J Malencik & Dave Hof
Time of inspection 9:00 ☒ a.m. ☐ p.m. to 1:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection 3/12/87 Weather conditions Clear & Warm
Acreage 11508 ☒ Permitted 42.5 ☒ Disturbed 0 ☒ Regraded 0 ☒ Seeded 42.5 ☒ Bonded
Enforcement Action

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☒	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☒	☐	☐	☒
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/018

Inspection Date 4/15/87

Please number comments to correspond with topics on previous page.

General Site Conditions: The mine site was in good condition and a few maintenance items are listed herein. These were discussed with Deer Creek Mine Official Val Payne.

Most of the snow had melted from the mine site. No runoff was observed from the disturbed areas.

Specific Observations

(1) Permit: The 8" water line has been installed. This was discussed in detail in inspection report dated 1/15/87. No problems were observed.

(4)(c) Sediment Pond. Water continues to discharge from from the sediment pond. This is taking place because of a leak in the shutoff valve. Previous inspection reports point that discharge will continue until the valve leak can be repaired. Access to the valve can only reasonably taken place when the pond is empty.

(4)(f) The mine operator is sampling and reporting this discharge as required by his NPDES Permit

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/018

Inspection Date 4/15/87

Please number comments to correspond with topics on previous page.

(4)(d) Other Sediment Control Measures. The silt fences along the conveyor belt line from the Powder Plant property line to the coal preparation held up well over the winter season. Typar silt fences were used and the installation, especially the silt fence supports were excellent. A heavy "chain link type" wire was used and the steel posts were very solid. Some minor maintenance needs to be performed on some of the silt fences in order to bring them up to standard.

Some of the straw bales along the aforementioned conveyor belt line also need a minor amount of maintenance.

(16) Roads (d) Maintenance. The class III short road spur from the main mine pad to the water tank is in need of spring maintenance. This also has equal application to drainage system immediately adjacent to the road. Gravel has been stockpiled in a suitable area adjacent to the this road. Mr. Payne stated the road work shall be undertaken as soon as weather permits.

Copy of report mailed to DONNA GRIFFIN, OSM; VAL PAYNE (BPC)

Copy of report given to Joe Helfrich, John Whitehead

Inspector's signature John W Whitehead for Wm Malencik No.

4-24-87

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

DOGM/IR-2

an equal opportunity employer

11/86 001049