



0005

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: Oct. 25, 1988
1:30 p.m. - 2:30 p.m.

Permittee and/or Operators Name: Utah Power and Light
Business Address: P.O. Box 310 Huntington, Utah 84528
Mine Name: Deer Creek Permit Number: ACT/015/018
Type of Mining Activity: Underground Surface Other
County: Emery State: Utah
Company Official(s): Guy Davis
State Official(s): Bill Warmack
Partial: Complete: Date of Last Inspection: September 12, 1988
Weather Conditions: Clear and warm
Acreage: Permitted 14620 Disturbed 26.5 Regraded Seeded Bonded 26.5
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	(X)	()	()	(X)
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	(X)	()	()	(X)
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	(X)	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/018

DATE OF INSPECTION October 25, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

The undersigned inspector was accompanied by Guy Davis (UP&L) on this partial inspection. A visit was made to both the Deer Creek Mine and Waste Rock Disposal Site.

1. PERMITS:

1. UP&L was issued a permit for the Deer Creek Mine and Waste Rock Disposal Site on September 13, 1988 effective through February 7, 1991. A performance bond of \$1,687,808 is filed with the DOGM.
2. Seven special conditions were attached for the Deer Creek Mine. Condition No. 6B states that UP&L shall provide, by October 31, 1988, an analysis of potential postmining discharge impact to surface drainages including mitigation measures where indicated. The remaining conditions will be referenced as required.

4c. SEDIMENT PONDS AND IMPOUNDMENTS:

The sediment pond was noted as containing water; cleanout is still pending completion of the waste rock site.

4e. SURFACE AND GROUND WATER MONITORING:

The installation of the mine discharge line is complete and all necessary roadway and embankment repairs have been made.

6. DEVELOPMENT WASTE AND SPOIL DISPOSAL:

1. Construction of the new waste rock storage site will commence within the next few days. Surveying and staking of the site was being completed during the inspection.
2. The Elk Canyon waste rock storage site was well compacted and graded. No associated erosion or instability problems were noted at this time.

Copy of this Report:

Mailed to: Guy Davis, UP&L

Mailed to SLC for: Brian Smith, OSM; Joe Helfrich, DOGM

Filed to: PFO

Inspectors Signature and Number: William A. Warmack #30 Date: Oct. 25, 1988

William A. Warmack 10/27/88