

8-16-99

0012



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Jch
8/22

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: July 19, 1988
10:30 a.m. to 12:00 p.m.

Permittee and/or Operators Name: Utah Power & Light Mining Division
Business Address: P.O. Box 310 Huntington, Utah 84528
Mine Name: Deer Creek Permit Number: ACT/015/018
Type of Mining Activity: Underground Surface Other
County: Emery State: Utah
Company Official(s): Val Payne
State Official(s): Bill Warmack and Pamela Grubaugh-Littig
Partial: Complete: Date of Last Inspection: June 15, 1988
Weather Conditions: Clear and warm
Acreage: Permitted 14620 Disturbed 26.5 Regraded Seeded Bonded 26.5
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/018

DATE OF INSPECTION July 19, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

The undersigned inspector was accompanied by Val Payne (UP&L) and Pamela Grubaugh-Littig (DOGM) on this partial inspection. The overall mine site conditions were found to be in good order, with follow-up repairs being completed per the previous inspection (June 15, 1988). Maintenance items listed herein do not constitute a violation of the UMC standards and are listed only as preventive measures.

1. PERMITS:

The operator has submitted a copy of the certificate of liability insurance to the Division as requested.

4b. DIVERSIONS:

Work is still being done on the highwall behind the bath house. Some additional material still needs to be removed to prevent further damage. The diversion will be re-established as soon as the slide material is dislodged and removed.

4c. SEDIMENT PONDS AND IMPOUNDMENTS:

Second quarter pond inspection was made on July 7, 1988 and indicated that the sediment level is nearing the 60 percent cleanout requirement; however, due to the lack of storage area, the pond will be cleaned after the new waste rock disposal site is approved and construction is complete. Cleanout should commence before the end of the calendar year.

Copy of this Report:

Mailed to: Val Payne, UP&L

Mailed to SLC for: Brian Smith, OSM; Joe Helfrich, DOGM

Filed to: PFO

Inspectors Signature and Number: William A. Warmack #30 Date: July 21, 1988