11-20-89

0002

RUS

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

ACT/015

Permit No. ACT/015/018

Inspection Date NOVEMBER 13, 1989

Permittee/Operator Name UTAH Power and LIGHT Company

Business Address P.O. BOX 310

City HUNTINGTON State UTAH Zip 84523

Mine DEER CREEK ☐ Surface ☒ Underground ☐ Other

County EMERY State UTAH

Company Official(s) Guy DAVIS

State Official(s) RICHARD V. SMITH

Time of inspection 10:00 ☒ a.m. ☐ p.m. to 3:00 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete

Date of last inspection OCTOBER 3, 1989 Weather conditions

Acreage 1466.0 ☑ Permitted 56 ☑ Disturbed ☐ Regraded ☐ Seeded 56 ☑ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☑	☐	☐	☑
2. Signs and markers	☑	■	☐	☐
3. Topsoil	☑	■	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☑	■	☐	☐
b Diversions	☑	☐	☐	☐
c Sediment ponds and impoundments	☑	☐	☐	☑
d Other sediment control measures	☑	☐	☐	☐
e Surface and groundwater monitoring	☑	☐	☐	☐
f Effluent limitations	☑	☐	☐	☐
5. Explosives	☑	☐	☐	☐
6. Development waste and spoil disposal	☑	☐	☐	☐
7. Coal processing waste	☐	☐	☑	☐
8. Noncoal waste	☑	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☑	☐	☐	☐
10. Slides and other damage	☐	☐	☑	☐
11. Contemporaneous reclamation	☑	☐	☐	☐
12. Backfilling and grading	☑	☐	☐	☐
13. Revegetation	☑	☐	☐	☐
14. Subsidence control	☑	☐	☐	☐
15. Cessation of operations	☐	☐	☑	☐
16. Roads				
a Construction	☑	☐	☐	☐
b Drainage controls	☑	☐	☐	☐
c Surfacing	☑	☐	☐	☐
d Maintenance	☑	☐	☐	☐
17. Other transportation facilities	☐	☐	☑	☐
18. Support facilities and utility installations	☑	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/018

Inspection Date November 13, 1989

Please number comments to correspond with topics on previous page.

1. Permits (Records Review): The review of records encompassed the following: Certificate of Insurance, 3rd Quarter Pond Inspection, 3rd Quarter Waste Rock Site Inspection, Water Monitoring Reports, UPDES Discharge Reports - 3rd Quarter, UPDES Permit, SPCC Plan, Reclamation and Bonding Agreement, Subsidence Monitoring (conducted 9/5/89), USFS Special Use Permits for tracks and parking/storage yard, State Lands Permit for 8" water line and seepage pits, BLM permit for 8" water line right-of-way, BLM permit for power line right-of-way. All paperwork was found to be in good order.

2c. Temporary sediment basin. Sediment has been removed and the basin has been infilled. The operator will reestablish the rip-rap channel and initiate re-seeding and mulching by no later than May 15, 1990 in accordance with the approved amendment.

Copy of report mailed to Brian Smith, OSM

Copy of report given to Guy Davis, UP&L; Joe Helfrich, DOGM

Inspector's signature Richard V. Smith No. 19

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer