0004

RVS

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/015/018
Inspection Date October 3, 1989

Permittee/Operator Name Utah Power and Light Company
Business Address P.O. Box 310
City Huntington State Utah Zip 84523
Mine Deer Creek ☐ Surface ☑ Underground ☐ Other
County Emery State Utah
Company Official(s) Guy Davis
State Official(s) Pamela Grubaugh-Littig
Time of inspection 11:00 ☑ a.m. ☐ p.m. to 1:00 ☐ a.m. ☑ p.m. ☑ Partial ☐ Complete
Date of last inspection September 12, 1989 Weather conditions Sunny
Acreage 14668 ☐ Permitted 56 ☑ Disturbed ☐ Regraded ☐ Seeded 56 ☑ Bonded
Enforcement Action NOV N89-20-1-1

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☑	☐	☐	☑
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☐	☐	☐	☐
c Sediment ponds and impoundments	☑	☐	☐	☑
d Other sediment control measures	☐	☐	☐	☐
e Surface and groundwater monitoring	☐	☐	☐	☐
f Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☑	☐	☐	☑
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☑	☐	☐	☑
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
a Construction	☑	☐	☐	☑
b Drainage controls	☐	☐	☐	☐
c Surfacing	☐	☐	☐	☐
d Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/018

Inspection Date October 3, 1989

Please number comments to correspond with topics on previous page.

1. A copy of the UPDES permit (authorized 2/11/88 and expiring 10/31/92) is on file at the Huntington office.
4c. The sedimentation pond Clemont is complete. About 6000 yards of sediment pond waste was buried at the Deer Creek Waste Rock Storage Site. The temporary sediment basin adjacent to the sedimentation pond still has water. When all the water has evaporated, the operator has committed to contemporaneously reclaim this area.
6. The Deer Creek Waste Rock Facility During the inspection, a UP&L employee was separating trash, as required, at the waste rock site. The water level at the waste rock pond is about three (3) feet below the spillway.
11. The fan access road area has been hydromulched, as of September 23, 1989.
16a. The county road to the Deer Creek Mine is currently being widened by the County. SEE NOV N89-20-1-1
6. Elk Canyon Storage Pad - The toe of the

Copy of report mailed to Brian Smith (OSM), Gary Davis (UP&L)

Copy of report given to PFO, Joe Helfrich (DOGM)

Inspector's signature Pamela Grubaugh-Littig (10/3/89) No. 20

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/018

Inspection Date October 3, 1989

Please number comments to correspond with topics on previous page.

Elk Canyon Storage Pad by the binwall is being repaired to meet the design requirements of slopes of 1.5:1

Copy of report mailed to Brian Smith (OSM), Guy Davis (UP&L)

Copy of report given to PFO, Jay Helfrich (DOGM)

Inspector's signature Pamela Grubaugh-Littig 10/3/89 No. 80

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer