7055

0010

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

RUS

inspection report

Permit No. ACT/015/018

Inspection Date JULY 20, 1989

Permittee/Operator Name UTAH POWER and LIGHT MINING DIVISION

Business Address P.O. BOX 310

City HUNTINGTON State UTAH Zip 84528

Mine DEER CREEK ☐ Surface ☑ Underground ☐ Other

County EMERY State UTAH

Company Official(s) GUY DAVIS

State Official(s) PAMELA GRUBAUGH-LITTIG

Time of inspection 8:00 ☑ a.m. ☐ p.m. to 3:00 ☐ a.m. ☑ p.m. ☐ Partial ☑ Complete

Date of last inspection JUNE 14, 1989 Weather conditions cloudy and warm

Acreage 14,620 ☑ Permitted 26.5 ☑ Disturbed ☐ Regraded ☐ Seeded ☐ Bonded

Enforcement Action

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	✓			✓
2. Signs and markers	✓			
3. Topsoil	✓			
4. Hydrologic balance				
a Stream channel diversions	✓			
b Diversions	✓			
c Sediment ponds and impoundments	✓			✓
d Other sediment control measures	✓			✓
e Surface and groundwater monitoring	✓			✓
f Effluent limitations	✓			✓
5. Explosives	✓			
6. Development waste and spoil disposal	✓			✓
7. Coal processing waste			✓	
8. Noncoal waste	✓			✓
9. Protection of fish, wildlife, and related environmental values	✓			
10. Slides and other damage	✓			
11. Contemporaneous reclamation	✓			
12. Backfilling and grading	✓			
13. Revegetation	✓			
14. Subsidence control	✓			
15. Cessation of operations			✓	
16. Roads				
— Construction	✓			
— Drainage controls	✓			
— Surfacing	✓			
— Maintenance	✓			
17. Other transportation facilities	✓			
18. Support facilities and utility installations	✓			✓
19. OTHER	✓			✓

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

DOGM/IR-1

an equal opportunity employer

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/018

Inspection Date July 20, 1989

Please number comments to correspond with topics on previous page.

1. Reviewed reports and permits pertaining to the Deer Creek Mine. All repots were in order.

4c. The second quarter pond inspection was completed June 30, 1989 and on file.

4d. The silt fence below the temporary sedimentation storage basin is operable but in need of repair. The silt fence opposite C-12 conveyor marker I-V-11 is thinning and needs replacement but is operable currently.

4e. Water monitoring reports were reviewed and found to be in good order.

a. In-mine water samples were collected June 6, 1989.

b. Sedimentation pond discharge samples were collected May 2, May 8, May 9, May 15, May 18, May 19, May 21, May 24, May 26, June 5, June 6, June 9, and June 12, 1989 and results reported.

c. Mine discharge sample was collected April 17 and June 15, 1989.

6. Disposal of the sedimentation pond waste (excess spoil) was being hauled to the new Deer Creek Waste.

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

an equal opportunity employer

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. _____

Inspection Date _____

Please number comments to correspond with topics on previous page.

6. Rock Storage Site and disposed in a designated portion of the waste rock site. Development waste was being hauled into two areas of the Waste Rock Storage Site.
Water ~~th~~ was noted in the containment pond at the waste rock storage site. This water had been trucked in from the decanted sedimentation pond.
4f. Three samples were taken (during the inspection) at the temporary ~~stor~~ sedimentation basin to determine if it meets effluent limitations. If it does, then this water may be used to water the roads. If not, the water will not be used to water roads.
8. Noncoal waste was being loaded and hauled to an approved landfill during the inspection.
18. The new substation is 80% complete. The leach field was observed during the inspection.
19. Current mining is in Federal Lease # SL-07-0645, U-02292.

Copy of report mailed to Guy Davis (UP:L) and Brian Smith (OSM)

Copy of report given to Joe Helfrich (DOGM); PFO; Brian

Inspector's signature Donald Durbaugh-Fitting 7/21/89 No. 20

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

DOGM/IR-2

an equal opportunity employer

11/86 001049