0014

533
7055

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

RVS

inspection report

Permit No. ACT/015/018

Inspection Date April 20, 1989

Permittee/Operator Name UTAH POWER & LIGHT MINING DIVISION

Business Address P.O. BOX 310

City HUNTINGTON State UT Zip 84528

Mine DEER CREEK ☐ Surface ☒ Underground ☐ Other

County EMERY State UT

Company Official(s) VAL PAYNE

State Official(s) BILL WARMACK

Time of inspection 11:30 ☒ a.m. ☐ p.m. to 12:30 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection MARCH 9, 1989 Weather conditions WARM

Acreage 14620 ☒ Permitted 26.5 ☒ Disturbed ☐ Regraded ☐ Seeded 26.5 ☒ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☐	☐	☐	☐
c Sediment ponds and impoundments	☒	☐	☐	☒
d Other sediment control measures	☒	☐	☐	☒
e Surface and groundwater monitoring	☐	☐	☐	☐
f Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☒	☐	☐	☒

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/018

Inspection Date 4/20/89

Please number comments to correspond with topics on previous page.

GENERAL: MR. VAL PAYNE (UP&L) ACCOMPANIED THE UNDERSIGNED INSPECTOR ON THIS PARTIAL INSPECTION AT THE NEW DEER CREEK WASTE ROCK FACILITY.

4c. CONSTRUCTION OF THE SEDIMENT POND AT THE SOUTHWEST CORNER OF THE SITE HAS COMMENCED.

4d. OTHER SEDIMENT CONTROLS: THE SILT FENCING ALONG THE OUTSLOPES OF THE ACCESS ROAD & DIKE HAS BEEN COMPLETED. HOWEVER, A FEW REPAIRS NEED TO BE MADE WHERE CROSSINGS HAVE OCCURRED.

13. REVEGETATION: THE CUT & FILL BANKS ALONG THE ACCESS ROAD & ALSO THE DIKE EMBANKMENTS HAVE BEEN SEEDED.

18. SUPPORT FACILITIES: THE PERIMETER FENCE AROUND THE SITE HAS BEEN INSTALLED WITH THE REQUIRED PERIMETER MARKERS.

Copy of report mailed to VAL PAYNE/GUY DAVIS (UP&L), JOE HEFFRICH (DOGM), BRIAN SMITH (OSM)

Copy of report given to PFO

Inspector's signature William A. Ubermeck 4/24/89 No. 30

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer