0022

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

gd pgl

inspection report

Permit No. ACT/015/018
Inspection Date April 10, 1990

Permittee/Operator Name Utah Power & Light Co.
Business Address P.O. Box 310
City Huntington State Ut Zip 84528
Mine Deer Creek ☐ Surface ☒ Underground ☐ Other
County Emery State Ut
Company Official(s) Guy Davis
State Official(s) Bill Malencik & Jess Kelley
Time of inspection 11:00 ☒ a.m. ☐ p.m. to 4:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection March 8/9, 1990 Weather conditions Clear/Warm
Acreage 14668 ☐ Permitted 56 ☐ Disturbed ☐ Regraded ☐ Seeded 56 ☐ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☐	☐	☐	☐
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☒	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☒	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☒	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☒	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/018

Inspection Date April 10, 1990

Please number comments to correspond with topics on previous page.

General Comments. The purpose of this inspection was two-fold, to conduct a partial inspection concentrating on the field segement and to give Jess Kelley the DOGM engineer an overview of the Deer Creek Mine.

Mine areas covered in this inspection included Rilda Cyn, the Deer Creek Mine, and the waste rock site.

Diversions. Some of the primary disturbed and undisturbed diversions were observed. No significant problems were noted.

Other Sediment Control. The sediment basin at the waste rock site contained water. No evidence that the basin had discharged. Sediment control along the beltline held up well over the winter and spring runoff. The operator mentioned he had walked the back side of the beltline.

Roads. The rills on the cut slopes approaching 9" in depth were observed at the waste rock access road. The operator discussed his drainage control plans he plans to implement in order to protect the cutslopes.

Copy of report mailed to UP&L/Guy Davis; SLC Fore; OSM/Brian Smith; DOGM/Joe Helfrich

Copy of report ~~given to~~ filed RFO

Inspector's signature Wm. J. Malencik No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

4/16/90