0030

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/015/018

Inspection Date Jan 4, 1990

Permittee/Operator Name UP&L

Business Address P.O. Box 310

City Huntington State Ut Zip 84528

Mine Deer Creek ☐ Surface ☒ Underground ☐ Other

County Emery State

Company Official(s) Guy Davis

State Official(s) Bill Malencik

Time of inspection 1:00 ☐ a.m. ☒ p.m. to 3:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection Dec 6, 1989 Weather conditions Cold/Windy

Acreage 14668 ☐ Permitted 56 ☐ Disturbed ☐ Regraded ☐ Seeded 56 ☐ Bonded

Enforcement Action None.

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☒	☐	☐	☒
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☒
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☒	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

DOGM/IR-1

an equal opportunity employer

11/86 001049

Note; DOGM File Copy Only- Another SAE/ANSA identified - Elk Canyon Area. Operator will add to pending areas now being compiled for a submission to the Division.

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/018

Inspection Date 1/4/90

Please number comments to correspond with topics on previous page.

General Comments: This partial inspection was conducted and both the mine site and the new waste rock areas were covered. The waste rock site was void of snow; less than 6" at the Deer Creek mine and confined to east & north slopes.

Signs & Markers: The ID Access Sign was moved from the Deer Creek Access Road & Control Gate to a point on the reconstructed highway where the permit boundary intersects the highway.

Sediment Pond: The sediment pond contained water, was stable and no problems noted.

Other Sediment Control: The silt basins at the waste rock site both contained water. The levels of water, as indicated by embankment signs, had been incidentally been reduced. The operator stated they had pumped the water from the basins and sprinkled the areas above that drain into the basins. This was done for a twofold reason - lower the water level and provide moisture to existing vegetation and small areas that had been seeded.

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/018

Inspection Date 1/4/90

Please number comments to correspond with topics on previous page.

Silt fences had recently been installed adjoining the reconstructed public highway. All were in good shape.
Development Waste & Spoil Disposal. The new waste rock is being utilized. Recent material includes mine bony & waste rock. Some of the recent material has pieces of props, bradish & other mine non-development or coal waste material. The operator stated that the non-coal waste material will be removed before the material will be spread and compacted.
Roads. Road cuts into the waste rock site need to be checked by the operator and if necessary steps taken to better handle runoff and/or stabilize rills.

Copy of report mailed to { UP&L -- Guy Davis
SLC: OSM/ Brian Smith; DOGM/Joe Helfrich

Copy of report ~~given to~~ filed PFO

Inspector's signature [signature] No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

1/5/90

DOGM/IR-2

an equal opportunity employer

11/86 001049