



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangertter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 360
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: November 27, 1991
12:30 pm - 1:30 pm

Permittee and/or Operators Name: PacifiCorp Electric Operations
Business Address: 201 S Main, Suite 2100, SLC, UT 84140-0021
Mine Name: Deer Creek Permit Number: ACT/015/018
Type of Mining Activity: Underground X Surface Other
County: Emery Federal Official(s): None
Company Official(s): Guy Davis
State Official(s): Ken Wyatt, Susan White
Partial: X Complete: Date of Last Inspection: 11/13/91
Weather Conditions: Clear and cool
Acreage: Permit 14,668 Disturbed 56 Regraded Seeded Bonded 56
Enforcement Action: Termination of NOV N91-7-1-1

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	(X)
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT

JP

(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/018

DATE OF INSPECTION: 11/27/91

(Comments are Numbered to Correspond with Topics Listed Above)

4d. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

Abatement of NOV #N91-7-1-1 required that the silt fences around the waste rock disposal area be repaired. This work had been completed. The additional areas along the waste rock disposal facility access road were also repaired. NOV #N91-7-1-1 was terminated.

16b. ROADS: DRAINAGE CONTROLS

The silt fences along the waste rock disposal area access road were repaired.

Copy of this Report:

Mailed to: Bernie Freeman (OSM), Blake Webster & Guy Davis (PEO)

Given to: Joe Helfrich (DOGM)

Inspectors Signature: _____

Ken Wyatt

#7

Date: 12/18/91