

0006



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter  
Governor  
Dee C. Hansen  
Executive Director  
Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

## INSPECTION REPORT

INSPECTION DATE & TIME: November 13, 1991  
8:10 a.m. - 10:00 p.m.

Permittee and/or Operators Name: PacifiCorp Electric Operations  
Business Address: One Utah Ctr, 201 S Main, #2100, SLC, UT 84140  
Mine Name: Deer Creek Permit Number: ACT/015/018  
Type of Mining Activity: Underground X Surface      Other       
County: Emery Federal Official(s): None  
Company Official (s): Guy Davis  
State Official(s): Ken Wyatt, Susan White, Henry Sauer  
Partial: X Complete:      Date of Last Inspection: 10/29-30/91  
Weather Conditions: Clear, cool  
Acreage: 14,668 Permit 56 Disturbed      Regraded      Seeded      Bonded 56  
Enforcement Action: modification of NOV N91-7-1-1

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	( )	( )	( )	( )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	( )	( )	( )
b. DIVERSIONS	( )	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	( )	(X)	( )	(X)
e. SURFACE AND GROUNDWATER MONITORING	(X)	( )	( )	(X)
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	(X)	( )	( )	(X)
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

INSPECTION REPORT

(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/018

DATE OF INSPECTION: November 13, 1991

(Comments are Numbered to Correspond with Topics Listed Above)

**4d. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES**

Abatement of NOV 91-7-1-1 required that the silt fences around the waste rock disposal area be repaired. This work had been completed. Several additional areas along the waste rock disposal facility access road were also in need of repair. Nov 91-7-1-1 was modified to include the entire waste rock site including the access road. The operator was given until November 26, 1991 to complete this work.

**4e. HYDROLOGIC BALANCE: SURFACE AND GROUNDWATER MONITORING**

The flume in Deer Creek (DCR04) measured .22 feet which corresponds to 1.15 CFS or 515.5 GPM.

**16b. ROADS: DRAINAGE CONTROLS**

The drainage from the waste rock disposal area's access road has impacted the silt fences in several places. The operator intends to repair these problems.

PLEASE NOTE:

This inspection report replaces a previous one in which the inspection was marked as a complete when it should have been marked as a partial.

Copy of this Report:

Mailed to: Bernie Freeman (OSM), Blake Webster & Guy Davis (PEO)

Given to: Joe Helfrich (DOGM)

Inspectors Signature: Ken Wyatt #7 Date: 11/26/91