0001

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

Partial: X Complete:___ Exploration:___
Inspection Date & Time: 12/29/92 11:30AM TO 1:00PM
Date of Last Inspection: 11/17/92

Mine Name: Deer Creek County: Emery Permit Number: ACT/015/018
Permittee and/or Operator's Name: PacifiCorp
Business Address: P.O. Box 1005, Huntington, Utah 84528
Type of Mining Activity: Underground X Surface___ Prep. Plant___ Other___
State Officials(s): Susan White
Company Official(s): Carl Housekeeper (permittee) and John Christensen (operator)
Federal Official(s): None
Weather Conditions: Cloudy and cold
Existing Acreage: Permitted-14,668 Disturbed-56 Regraded-___ Seeded-___ Bonded-56
Increased/Decreased: Permitted-___ Disturbed-___ Regraded-___ Seeded-___ Bonded-___
Status: __Exploration/ X Active/__Inactive/__Temporary Cessation/__Bond Forfeiture
Reclamation (__Phase I/__Phase II/__Final Bond Release/__Liability_____Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
   a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
   b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[ ]	[ ]	[ ]	[ ]
2. SIGNS AND MARKERS	[X]	[ ]	[X]	[ ]
3. TOPSOIL	[ ]	[ ]	[ ]	[ ]
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	[ ]	[ ]	[ ]	[ ]
b. SEDIMENT PONDS AND IMPOUNDMENTS	[ ]	[ ]	[ ]	[ ]
c. OTHER SEDIMENT CONTROL MEASURES	[ ]	[ ]	[ ]	[ ]
d. WATER MONITORING	[ ]	[ ]	[ ]	[ ]
e. EFFLUENT LIMITATIONS	[ ]	[ ]	[ ]	[ ]
5. EXPLOSIVES	[ ]	[ ]	[ ]	[ ]
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[ ]	[ ]	[ ]	[ ]
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[ ]	[ ]	[ ]	[ ]
8. NONCOAL WASTE	[ ]	[ ]	[ ]	[ ]
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	[ ]	[ ]	[ ]	[ ]
10. SLIDES AND OTHER DAMAGE	[ ]	[ ]	[ ]	[ ]
11. CONTEMPORANEOUS RECLAMATION	[ ]	[ ]	[ ]	[ ]
12. BACKFILLING AND GRADING	[ ]	[ ]	[ ]	[ ]
13. REVEGETATION	[X]	[ ]	[X]	[ ]
14. SUBSIDENCE CONTROL	[ ]	[ ]	[ ]	[ ]
15. CESSATION OF OPERATIONS	[ ]	[ ]	[ ]	[ ]
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	[ ]	[ ]	[ ]	[ ]
b. DRAINAGE CONTROLS	[ ]	[ ]	[ ]	[ ]
17. OTHER TRANSPORTATION FACILITIES	[ ]	[ ]	[ ]	[ ]
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	[X]	[ ]	[X]	[ ]
19. AVS CHECK (4th Quarter-April, May, June)_____(date)	[ ]	[ ]	[ ]	[ ]
20. AIR QUALITY PERMIT	[ ]	[ ]	[ ]	[ ]
21. BONDING & INSURANCE	[ ]	[ ]	[ ]	[ ]

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: ACT/015/018 DATE OF INSPECTION: 12/29/92

(Comments are Numbered to Correspond with Topics Listed Above)

Approximately 12 inches of snow had fallen on site the day prior to this inspection. Most all diversions, and sediment control measures were covered with snow and no runoff had occurred.

2. SIGNS AND MARKERS

The permit signs were in place. The permit sign at the entrance to the Waste Rock site had been turned by either wind or an individual. The operator was asked to fix the sign so it could not be turned. The owner is listed on the sign as Pacificorp Electric Operations and the operator is Energy West Mining Company.

13. REVEGETATION

The permittee stated that no interim or permanent seeding had occurred in 1992.

18. SUPPORT FACILITIES/UTILITY INSTALLATIONS

The operator stated that the storage boxes were being completed the day of the inspection.

Copy of this Report:
Mailed to: Bernie Freeman (OSM), Carl Housekeeper (PacifiCorp)
Given to: Joe Helfrich (DOGM)

Inspector's Signature: Susan M. White #35 Date: 1/5/93