

0271

Rev'd Done  
7/8/99

0009

1998 Annual Report Review

Permittee: Energy West Mining Co.  
 Mine Name: Deer Creek Mine  
 Permit Number: ACT/015/018  
 Date Report Received: 4/30/99, DOGM-SLO 5/5/99 DOGM-PFO

Instructions: The assigned staff will review their respective portions of the Annual report and provide a written determination (findings) on how the Mine has or has not met the permit requirements for reporting. If the report is deficient or remedial action is required to obtain compliance, this should be noted and the inspector notified. Once all reviewers have completed the report, a copy will be filed in the Mine folder #6.

Assigned Reviewers: Peter Hess, Engineer/Inspector \*

	Section to review	Submitted	Yes	No	Findings
*	Cover sheet		✓	—	Cover sheets appear adequate.
*	AVS; Legal/Financial Update		✓	—	Report appears adequate + accurate.
*	Mine Sequence Map		✓	—	Map <u>not</u> P.E. certified
	Water Monitoring Data		—	—	
	Precipitation & Climatological Data		—	—	
	Non-Coal Waste		—	—	
*	Subsidence monitoring data		✓	—	Ten areas monitored for subsidence relative to mining indeed at Deer Creek. Report appears adequate.
*	Annual Impoundment Certification / Waste Rock Sites		✓	—	All quarterly impoundment inspections for 1998 submitted; all signed by John Christensen, P.E.
*	Annual Overburden, Spoil, Refuse, Floor, etc.		✓	—	Report submitted in Appendix E. Should be reviewed by R. Davidson.
	Vegetation data		—	—	
	Revegetation Success monitoring		—	—	