

INSPECTION REPORT

Partial XXX Complete Exploration
 Inspection Date: 03/26/2003 Time: 9:30 am-12:30 pm
 Date of Last Inspection: 02/14/2003

Mine Name: Deer Creek Mine County: Emery Permit Number: C/015/018
 Permittee and/or Operator's Name: PacifiCorp
 Business Address: P.O. Box 310, Huntington, Utah 84528
 Company Official(s): Dennis Oakley
 State Official(s): Stephen J. Demczak Federal Official(s): None
 Weather Conditions: Cloudy, 40's
 Type of Mining Activity: Underground XXX Surface Prep Plant Other
 Existing Acreage: Permitted 24,638.52 Disturbed 95.79 Regraded Seeded
 Status: Active

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2.	SIGNS AND MARKERS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3.	TOPSOIL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b.	SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
c.	OTHER SEDIMENT CONTROL MEASURES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
d.	WATER MONITORING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
e.	EFFLUENT LIMITATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5.	EXPLOSIVES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8.	NONCOAL WASTE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9.	PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL ISSUES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10.	SLIDES AND OTHER DAMAGE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11.	CONTEMPORANEOUS RECLAMATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12.	BACKFILLING AND GRADING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13.	REVEGETATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14.	SUBSIDENCE CONTROL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15.	CESSATION OF OPERATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b.	DRAINAGE CONTROLS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17.	OTHER TRANSPORTATION FACILITIES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19.	AVS CHECK (4 th Quarter- April, May, June)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20.	AIR QUALITY PERMIT	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21.	BONDING & INSURANCE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT
(Continuation Sheet)

PERMIT NUMBER: C/015/018

DATE OF INSPECTION: 03/26/2003

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The CTS system shows two permit actions with the Deer Creek Mine. These are: Volume 1 to reduce the permit area and Modify Exploration Plan. The Division is waiting for a letter from the BLM to continue the review on Volume 1 and the permittee is addressing deficiencies for Modify Exploration Plan. The Mill Fork application was approved March 5, 2003.

3. TOPSOIL

I inspected the waste rock area. The permittee was installing new silt fences for the protection of the topsoil. The topsoil pile showed no signs of wind or water erosion.

4A. HYDROLOGIC BALANCE: DIVERSIONS

The diversions were spot-checked and were functioning as designed. Several silt fences along the belt conveyor leading to the power plant will need to be cleaned out in the near future. Sediment has started to build-up behind the fences. The permittee has committed in cleaning out the silt fences.

Two culverts at the mine site were beginning to get plugged. The permittee has committed in cleaning out these drop drain culverts.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

No sediment ponds were discharging during the inspection. I noticed no hazardous conditions at the sediment ponds.

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

The permittee and I inspected the active refuse pile. We noticed no hazardous conditions. The permittee was in the process of transporting additional refuse material to the site.

8. NONCOAL WASTE

The mine site area had a little non-coal waste material. The permittee has committed in cleaning up the material.

18. SUPPORT FACILITIES/UTILITY INSTALLATIONS

The facilities have no new construction since the last inspection.

Inspector's Signature: _____ Date: March 27, 2003
Stephen J. Demczak #39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM
Chuck Semborski, PacifiCorp
Price Field office

O:\015018.DER\Compliance\2003\p_0326.doc