



State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

Table with 2 columns: Role, Name. Row 1: Company, Dennis Oakley, Environmental Engineer. Row 2: OGM, Steve Demczak, Environmental Scientist III.

Inspection Report

Table with 2 columns: Field, Value. Fields include Permit Number (C0150018), Inspection Type (PARTIAL), Inspection Date (Tuesday, July 19, 2005), Start Date/Time (7/19/2005 10:00:00 AM), End Date/Time (7/19/2005 2:00:00 PM), Last Inspection (Monday, June 20, 2005).

Inspector: Steve Demczak, Environmental Scientist III

Weather: Sunny, 90's

InspectionID Report Number: 673

Accepted by: pgrubaug
7/27/2005

Permittee: PACIFICORP
Operator: ENERGY WEST MINING CO
Site: DEER CREEK MINE
Address: PO BOX 310, HUNTINGTON UT 84528
County: EMERY
Permit Type: PERMANENT COAL PROGRAM
Permit Status: ACTIVE

Current Acreages

Table with 2 columns: Value, Description. Values: 22,769.06 (Total Permitted), 84.34 (Total Disturbed), Phase I, Phase II, Phase III.

Mineral Ownership

- Checked: Federal, State, Fee. Unchecked: County, Other.

Types of Operations

- Checked: Underground. Unchecked: Surface, Loadout, Processing, Reprocessing.

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Permit Conditions:

- 1) During entry development if sustained quantities of groundwater are encountered which are greater than 5 gpm from a single source...
2) Vehicle access will not be allowed in Rilda Canyon from December 1 to April 15 for construction and/or maintenance...
3) PacifiCorp will submit water quality data for the Deer Creek Mine in an electronic format through the EDI web site.

The permittee is meeting these conditions at this time.

Permitting Actions - New Surface Facilities in Rilda Canyon
Violations: None

Inspector's Signature

Date Tuesday, July 26, 2005

Steve Demczak, Environmental Scientist III
Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

2. Signs and Markers

Identification signs were inspected at the gate to the refuse pile. The information was complete.

3. Topsoil

The topsoil piles at the refuse pile area was inspected with no signs of wind or water erosion. Some vegetation was growing on the piles.

4.a Hydrologic Balance: Diversions

The diversions were spot-checked throughout the property and were functioning as designed.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The sediment pond at the mine site was inspected with no hazardous conditions noticed during the inspection.

4.c Hydrologic Balance: Other Sediment Control Measures

Silt fences and sediment traps were inspected along the belt line. They have been recently cleaned out and would function during a rain storm.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile was inspected and no hazardous conditions were noticed during the inspection.

8. Noncoal Waste

The area was generally cleaned from non-coal waste materials.

18. Support Facilities, Utility Installations

The permittee would like to open portal breakouts at Rilda Canyon for ventilation as soon as possible. It is becoming difficult to ventilate the longwall and continuous miner sections.