0039

State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

Representatives Present During the Inspection:		
Company	Dennis Oakley	Environmental Engineer
OGM	Karl Houskeeper	Environmental Scientist III

Inspection Report

Permit Number:	C0150018
Inspection Type:	PARTIAL
Inspection Date:	Monday, December 15, 2008
Start Date/Time:	12/15/2008 9:00:00 AM
End Date/Time:	12/15/2008 1:00:00 PM
Last Inspection:	Monday, November 24, 2008

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Overcast/Snowing, Temp. 12 Deg. F.

InspectionID Report Number: 1862

Accepted by: Jhelfric
1/6/2009

Permitee: **PACIFICORP**
Operator: **ENERGY WEST MINING CO**
Site: **DEER CREEK MINE**
Address: **PO BOX 310, HUNTINGTON UT 84528**
County: **EMERY**
Permit Type: **PERMANENT COAL PROGRAM**
Permit Status: **ACTIVE**

Current Acreages

19,722.21	Total Permitted
98.05	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- [x] Federal
- [x] State
- [ ] County
- [x] Fee
- [ ] Other

Types of Operations

- [x] Underground
- [ ] Surface
- [ ] Loadout
- [ ] Processing
- [ ] Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature: Karl R. Houskeeper **Date** Monday, December 15, 2008

Karl Houskeeper, Environmental Scientist III
Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • *www.ogm.utah.gov*

Permit Number: C0150018
Inspection Type: PARTIAL
Inspection Date: Monday, December 15, 2008

Inspection Continuation Sheet

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. *Substantiate the elements on this inspection by checking the appropriate performance standard.*
   a. *For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.*
   b. *For PARTIAL inspections check only the elements evaluated.*
2. *Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.*
3. *Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.*
4. *Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.*

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	☐	☐	☐	☐
2. Signs and Markers	☑	☐	☑	☐
3. Topsoil	☐	☐	☐	☐
4.a Hydrologic Balance: Diversions	☑	☐	☐	☐
4.b Hydrologic Balance: Sediment Ponds and Impoundments	☐	☐	☐	☐
4.c Hydrologic Balance: Other Sediment Control Measures	☐	☐	☐	☐
4.d Hydrologic Balance: Water Monitoring	☑	☐	☑	☐
4.e Hydrologic Balance: Effluent Limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Disposal of Excess Spoil, Fills, Benches	☐	☐	☐	☐
7. Coal Mine Waste, Refuse Piles, Impoundments	☑	☐	☐	☐
8. Noncoal Waste	☑	☐	☑	☐
9. Protection of Fish, Wildlife and Related Environmental Issues	☐	☐	☐	☐
10. Slides and Other Damage	☐	☐	☐	☐
11. Contemporaneous Reclamation	☐	☐	☐	☐
12. Backfilling And Grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence Control	☐	☐	☐	☐
15. Cessation of Operations	☐	☐	☐	☐
16.a Roads: Construction, Maintenance, Surfacing	☐	☐	☐	☐
16.b Roads: Drainage Controls	☐	☐	☐	☐
17. Other Transportation Facilities	☐	☐	☐	☐
18. Support Facilities, Utility Installations	☑	☐	☑	☐
19. AVS Check	☐	☐	☐	☐
20. Air Quality Permit	☐	☐	☐	☐
21. Bonding and Insurance	☐	☐	☐	☐
22. Other	☐	☐	☐	☐

2. Signs and Markers

The ID signs contained the necessary information. New signs have been installed with updated address information.

4.d Hydrologic Balance: Water Monitoring

Third quarter 2008 water monitoring information is in the EDI website and has been uploaded. Water monitoring is current.

8. Noncoal Waste

Noncoal waste items were collected and disposed of properly in the designated storage facility.

18. Support Facilities, Utility Installations

Rilda Canyon support facilities were inspected as part of the partial inspection. The facilities were well maintained. A light snow was occurring during the inspection.