



State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report

Permit Number:	C0150018
Inspection Type:	COMPLETE
Inspection Date:	Tuesday, November 15, 2011
Start Date/Time:	11/15/2011 9:00:00 AM
End Date/Time:	11/15/2011 1:00:00 PM
Last Inspection:	Wednesday, October 26, 2011

Representatives Present During the Inspection:	
Company	Guy Davis
OGM	Karl Houskeeper

Inspector: Karl Houskeeper

Weather: Clear, Temp. 44 Deg. F.

InspectionID Report Number: 2924

Accepted by: jhelfric

11/29/2011

Permitee: **ENERGY WEST MINING CO**
 Operator: **ENERGY WEST MINING CO**
 Site: **DEER CREEK MINE**
 Address: **PO BOX 310, HUNTINGTON UT 84528**
 County: **EMERY**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **ACTIVE**

Current Acreages

19,936.88	Total Permitted
97.45	Total Disturbed
0.60	Phase I
0.60	Phase II
0.60	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing


Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Karl R. Houskeeper

Inspector's Signature:

Karl Houskeeper,
Inspector ID Number: 49

Date Tuesday, November 15, 2011



REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

The current DOGM permit C/015/0018 was issued effective 02/07/2011 and expires 02/07/2016.

-Certificate of Insurance policy number X0720A1A11, issued 08/28/2011 and terminates 08/28/2012.

-UPDES permit # UT0023604 effective 12/01/2007 and expires @ midnight 11/30/2012.

-Air Quality permit DAQE-AN0239003-02, issued June 14, 2002.

-SPCC Plan dated 01/27/2009. The Plan is P.E. certified, stamped, signed and dated by a Utah P.E.

2. Signs and Markers

The mine identification signs are located at points of public access to the permit area. The signs contain the required information.

4.a Hydrologic Balance: Diversions

The diversion off of the waste rock site needs to be opened at the inlet.

A minimal amount of snow has been pushed into the parking lot diversion. The amount of snow currently present is not enough to prevent flow or create a blockage. However in the future if snow is pushed into the diversion and creates an obstruction a violation will be issued to address the problem. Measures should be taken now to prevent future occurrences.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Third quarter 2011 sediment pond inspections were done on September 22, 2011. The Rilda Facilities sediment pond inspection report for third quarter 2011 does not contain an elevation for 60%, 100% and existing sediment level. This condition has been noted in the past by reviewi of previous quarterly inspections reports and needs to be taken care of.

4.c Hydrologic Balance: Other Sediment Control Measures

Sections of silt fence at the waste rock site were observed down or ripped. The silt fences require maintenance.

4.e Hydrologic Balance: Effluent Limitations

Reviewed the September 2011 discharge monitoring reports. No problems were noted on the reports.

7. Coal Mine Waste, Refuse Piles, Impoundments

Third quarter 2011 refuse pile inspection was done on September 22, 2011 for the Waste Rock Site .

8. Noncoal Waste

Observed minimal trash outside of the noncoal storage area during the inspection.

20. Air Quality Permit

Approval order AN0239003-02 was issued on 06/14/2002 and remains in effect.

21. Bonding and Insurance

The bond is set at \$4,113,000. It includes the new Rilda Facilities. The bond was recently raised by \$5,000 by the installation of the approved switch gear in Rilda Canyon. There are 19,722.21 permitted acres of which 98.05 are disturbed acres.

22. Other

From: Karl Houskeeper
To: Ken.Fleck@PacifiCorp.com
CC: DARONHADDOCK@utah.gov; OGMCOAL@utah.gov
Date: 11/29/2011 2:50 PM
Subject: November 2011 Inspection Report
Attachments: Deer Creek 11152011.pdf

Ken,

Attached is the November 2011 inspection report for Deer Creek.

Thanks,
Karl