

Outgoing
CO150018
K

Suzanne Steab - August 2011 Inspection Report

From: Karl Houskeeper
To: Ken.Fleck@PacifiCorp.com
Date: 9/15/2011 2:02 PM
Subject: August 2011 Inspection Report
CC: ANGELANANCE@utah.gov; DARONHADDOCK@utah.gov; SUZANNESTEAB@utah.gov
Attachments: Deer Creek August 2011.pdf

Ken,

Attached is the August 2011 inspection report for Deer Creek.

Thanks,
Karl



State of Utah
DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report

Permit Number:	C0150018
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, August 23, 2011
Start Date/Time:	8/23/2011 8:00:00 AM
End Date/Time:	8/23/2011 12:00:00 PM
Last Inspection:	Monday, July 11, 2011

Representatives Present During the Inspection:	
Company	Guy Davis
OGM	Karl Houskeeper

Inspector: Karl Houskeeper

Weather: Clear, Temp. 72 Deg. F.

InspectionID Report Number: 2840

Accepted by: jheltric
 9/14/2011

Permitee: **ENERGY WEST MINING CO**
 Operator: **ENERGY WEST MINING CO**
 Site: **DEER CREEK MINE**
 Address: **PO BOX 310, HUNTINGTON UT 84528**
 County: **EMERY**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **ACTIVE**

Current Acreages		Mineral Ownership	Types of Operations
19,740.78	Total Permitted	<input checked="" type="checkbox"/> Federal	<input checked="" type="checkbox"/> Underground
98.05	Total Disturbed	<input checked="" type="checkbox"/> State	<input type="checkbox"/> Surface
0.60	Phase I	<input type="checkbox"/> County	<input type="checkbox"/> Loadout
	Phase II	<input checked="" type="checkbox"/> Fee	<input type="checkbox"/> Processing
	Phase III	<input type="checkbox"/> Other	<input type="checkbox"/> Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Karl R. Houskeeper

Date Tuesday, August 23, 2011

Karl Houskeeper,
 Inspector ID Number: 49

Note: This inspection report is not a final determination of compliance with the regulatory program of the Division of Oil, Gas and Mining.
 telephone (801) 538-3340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov



Permit Number: C0150018
 Inspection Type: PARTIAL
 Inspection Date: Tuesday, August 23, 2011

Inspection Continuation Sheet

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Permit Number: C0150018
Inspection Type: PARTIAL
Inspection Date: Tuesday, August 23, 2011

Inspection Continuation Sheet

Page 3 of 3

2. Signs and Markers

Observed the mine identification signs located at the waste rock site and the main facilities. Both signs contained the required information.

4.a Hydrologic Balance: Diversions

A erosional cut was observed over top of the embankment encasing the culvert by the old truck loadout and slotted road trench. Works were on hand and started making repairs durin the inspection.

4.c Hydrologic Balance: Other Sediment Control Measures

A weak berm was noticed on the ROM bench. Repairs need to be made to prevent water being diverted over the slope.

7. Coal Mine Waste, Refuse Piles, Impoundments

The road on the waste roke pad has been moved to the south and no longer disects the north and south pile. The two piles will now continue to merge until their capacity is reached.