



# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

### Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

# Inspection Report

Permit Number:	<b>C0150018</b>
Inspection Type:	COMPLETE
Inspection Date:	Thursday, February 04, 2016
Start Date/Time:	2/4/2016 8:00:00 AM
End Date/Time:	2/4/2016 12:00:00 PM
Last Inspection:	Wednesday, January 20, 2016

Representatives Present During the Inspection:	
Company	Dennis Oakley
OGM	Karl Houskeeper

Inspector: Karl Houskeeper

Weather: Overcast/Snowing, Temp, 10 Deg. F.

InspectionID Report Number: 5426

Accepted by: JHELFRIC

2/8/2016

Permitee: **PACIFICORP**  
 Operator: **INTERWEST MINING CO**  
 Site: **DEER CREEK MINE**  
 Address: **PO BOX 310, HUNTINGTON UT 84528**  
 County: **EMERY**  
 Permit Type: **PERMANENT COAL PROGRAM**  
 Permit Status: **ACTIVE**

#### Current Acreages

19,936.88	<b>Total Permitted</b>
91.63	<b>Total Disturbed</b>
0.60	<b>Phase I</b>
0.60	<b>Phase II</b>
0.60	<b>Phase III</b>

#### Mineral Ownership

- Federal
- State
- County
- Fee
- Other

#### Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

#### Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The complete inspection was initiated by the Division inspector stopping at the operators office located on main street of Huntington, Utah, where the Interwest Employees are located. A review of the records for the Deer Creek mine took place in the office. Dennis Oakley provided the information required for the paperwork portion of the complete inspection. Dennis was also present for the field inspection.

*Karl R. Houskeeper*

Inspector's Signature:

Karl Houskeeper,  
Inspector ID Number: 49

Date Thursday, February 04, 2016



**REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS**

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

## **1. Permits, Change, Transfer, Renewal, Sale**

Division of Oil, Gas & Mining Permit C/015/0018 issued January 10, 2014 and expires February 7, 2016.

UPDES Permit Ut0023604 effective February 1, 2015 and expires at midnight on January 31, 2020.

SPCC Plan is dated December 2010. The spill plan is P.E. dated, stamped and signed by a registered P.E. in the State of Utah.

Air Quality Permit DAQE-AN0239003-02 issued on June 14, 2002 still remains effective for the mine site.

The current bond is \$3,374,000.

Insurance coverage is through Associated Electric and Gas Insurance Service LTD. The insurance is effective 10/01/2015 and expires 10/01/2016. Minimum required insurance coverage amounts have been met. The certificate holder is The State of Utah. The cancelation clause is in accordance with Division policy. The insurance coverage includes explosion coverage.

Reclamation agreement is covered with Bond # 103908970. Signed by both parties July 25, 2005.

## **2. Signs and Markers**

Mine identification signs have been updated with new owner/operator information and addresses/phone numbers. Identification signs are posted at entrances into the mining permit area. Signs are compliant.

### **4.a Hydrologic Balance: Diversions**

Entire site is snow covered, including all of the diversions.

### **4.b Hydrologic Balance: Sediment Ponds and Impoundments**

The fourth quarter 2015 sediment pond inspections were completed as follows: Mine pond 12/10/2015. Rilda pond 12/10/2015. Waste rock pond 11/16/2015.

### **4.e Hydrologic Balance: Effluent Limitations**

The discharge monitoring reports for September, October and November 2015 were reviewed.. No problems were noted.

## **7. Coal Mine Waste, Refuse Piles, Impoundments**

The 4th quarter 2015 refuse pile/waste rock inspections were completed as follow: Elk Canyon and Old waste rock site done on 12/17/2015. The main waste rock site done on 11/26/2015.

Permit Number: C0150018  
Inspection Type: COMPLETE  
Inspection Date: Thursday, February 04, 2016

**20. Air Quality Permit**

Air Quality Permit DAQE-AN0239003-02 issued on June 14, 2002 still remains effective for the mine site.

**21. Bonding and Insurance**

The current bond is \$3,374,000.