



State of Utah
 DEPARTMENT OF NATURAL RESOURCES
 MICHAEL R. STYLER
Executive Director
Division of Oil, Gas and Mining
 JOHN R. BAZA
Division Director

Inspection Report

Permit Number:	C0150018
Inspection Type:	COMPLETE
Inspection Date:	Wednesday, August 10, 2016
Start Date/Time:	8/10/2016 8:30:00 AM
End Date/Time:	8/10/2016 1:00:00 PM
Last Inspection:	Monday, July 11, 2016

Representatives Present During the Inspection:	
Company	Kenneth Fleck
OGM	Karl Houskeeper

Inspector: Karl Houskeeper
 Weather: Cloudy, Temp. 82 Deg. F.
 InspectionID Report Number: 5600
 Accepted by: JHELFRIC
 8/29/2016

Permitee: **PACIFICORP**
 Operator: **INTERWEST MINING CO**
 Site: **DEER CREEK MINE**
 Address: **PO BOX 310, HUNTINGTON UT 84528**
 County: **EMERY**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **ACTIVE**

Current Acreages	
19,940.60	Total Permitted
91.63	Total Disturbed
0.60	Phase I
0.60	Phase II
0.60	Phase III

- Mineral Ownership**
- Federal
 - State
 - County
 - Fee
 - Other

- Types of Operations**
- Underground
 - Surface
 - Loadout
 - Processing
 - Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Karl R. Houskeeper

Inspector's Signature:

Karl Houskeeper,
 Inspector ID Number: 49

Date Wednesday, August 10, 2016



REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

Division of Oil, Gas & Mining Permit C/015/0018 issued February 7, 2016 and expires February 7, 2021.

UPDES Permit Ut0023604 effective February 1, 2015 and expires at midnight on January 31, 2020.

SPCC Plan is dated June 2016. The spill plan is P.E. dated, stamped and signed by a registered P.E. in the State of Utah.

Air Quality Permit DAQE-AN0239003-02 issued on June 14, 2002 still remains effective for the mine site.

The current bond is \$3,374,000.

Insurance coverage is through Associated Electric and Gas Insurance Service LTD. The insurance is effective 10/01/2015 and expires 10/01/2016. Minimum required insurance coverage amounts have been met. The certificate holder is The State of Utah. The cancelation clause is in accordance with Division policy. The insurance coverage includes explosion coverage.

Reclamation agreement is covered with Bond # 103908970. Signed by both parties July 25, 2005.

2. Signs and Markers

The mine identification signs at the Main Facility, Waste Rock site and Rilda Portal area were checked during the complete inspection and found to be in compliance.

4.a Hydrologic Balance: Diversions

The majority of the diversions at the Main Facility have been cleaned, re-graded or re-constructed following a high intensity storm that entered the permit area from the undisturbed area. The culvert system around the shop and bath house area still needs to be cleaned using a vacuum truck.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The sediment pond was not impacted by the undisturbed storm flow that entered the permit area. The main sediment pond was inspected on 6/15/16 for the second quarter of 2016. The waste rock and rilda canyon sediment ponds were inspected on 6/14/16 for the second quarter of 2016

4.e Hydrologic Balance: Effluent Limitations

The discharge monitoring reports for April, May and June 2016 were checked during the paperwork review. The reports have been submitted to DEQ.

Permit Number: C0150018
Inspection Type: COMPLETE
Inspection Date: Wednesday, August 10, 2016

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile was inspected April 26, 2016. No problems were noted. This inspection serves as the second quarter 2016 inspection.

20. Air Quality Permit

Air Quality Permit DAQE-AN0239003-02 issued on June 14, 2002 still remains effective for the mine site.

21. Bonding and Insurance

The current bond is \$3,374,000.




Road Diversion looking Up Canyon Main Road




Road Diversion looking Down canyon Main Road



Culvert Inlet Below Truck Load Out




Parking Lot



Yard Area



Diversion and Drop Inlet Main Access Road



Road Diversion above C1/C2 Transfer