



GARY R. HERBERT
Governor

GREG BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report

Permit Number:	C0150018
Inspection Type:	COMPLETE
Inspection Date:	Tuesday, August 15, 2017
Start Date/Time:	8/15/2017 8:30:00 AM
End Date/Time:	8/15/2017 12:00:00 PM
Last Inspection:	Tuesday, July 18, 2017

Inspector: Karl Houskeeper,

Weather: Overcast, Temp. 67 Deg. F.

InspectionID Report Number: 5923

Accepted by: DHADDOCK
8/31/2017

Permitee: **PACIFICORP**
 Operator: **INTERWEST MINING CO**
 Site: **DEER CREEK MINE**
 Address: **PO BOX 310, HUNTINGTON UT 84528**
 County: **EMERY**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **ACTIVE**

Current Acreages

20,308.10	Total Permitted
91.63	Total Disturbed
0.60	Phase I
0.60	Phase II
0.60	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Date Tuesday, August 15, 2017

Karl Houskeeper,
Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.
telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov



REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

Division of Oil, Gas & Mining Permit C/015/0018 issued February 7, 2016 and expires February 7, 2021.

UPDES Permit Ut0023604 effective February 1, 2015 and expires at midnight on January 31, 2020.

SPCC Plan is dated June 2016. The spill plan is P.E. dated, stamped and signed by a registered P.E. in the State of Utah.

Air Quality Permit DAQE-AN0239003-02 issued on June 14, 2002 still remains effective for the mine site.

The current bond is \$3,374,000.

Insurance coverage is through Associated Electric and Gas Insurance Service LTD. The insurance is effective 10/01/2016 and expires 10/01/2017. Minimum required insurance coverage amounts have been met. The certificate holder is The State of Utah. The cancelation clause is in accordance with Division policy. The insurance coverage includes explosion coverage.

Reclamation agreement is covered with Bond # 103908970. Signed by both parties July 25, 2005.

2. Signs and Markers

Mine identification signs were observed at points of access from the public into the mining permit area. These signs contained the name, address, Phone number and mining permit number of the operator as required by law. The signs are in compliance with the requirements of the law. Signs are posted at the waste rock site, main mine facility, and rilda facility.

4.a Hydrologic Balance: Diversions

The road diversion located at the waste rock site has been maintained since the prior inspection.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The waste rock sediment pond was inspected for the first quarter of 2017 on 17th January 2017 and PE. Certified on 30th January 2017, by Richard White a Utah P.E. No problems were noted.

The Main sediment pond was inspected on 6/16/17. The Rilda sediment pond were inspected on 6/13/17. The waste rock sediment pond was inspected on 6/23/17. These inspections were done for the second quarter of 2017. No problems were noted.

The existing sediment level for all ponds is below the 60% elevation used to determine when the ponds need to be cleaned.

4.e Hydrologic Balance: Effluent Limitations

The discharge monitoring reports for June 2017 were reviewed. The reports were submitted to DEQ in accordance with their policy.

5. Explosives

No explosives are being stored at the mine site.

7. Coal Mine Waste, Refuse Piles, Impoundments

The main waste rock site was inspected on the 23rd January 2017 and Utah P.E. Certified by Richard White. No problems were noted. This is the second quarter 2017 waste rock inspection.

The Original Site & Elk Canyon waste rock sites were abandoned by MSHA on April 12, 2016.

20. Air Quality Permit

Air Quality Permit DAQE-AN0239003-02 issued on June 14, 2002 still remains effective for the mine site.

21. Bonding and Insurance

The current bond is \$3,374,000.