GARY R. HERBERT
Governor
GREG BELL
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
MICHAEL R. STYLER
Executive Director
Division of Oil, Gas and Mining
JOHN R. BAZA
Division Director

Inspection Report

Permit Number:	**C0150018**
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, September 26, 2017
Start Date/Time:	9/26/2017 8:30:00 AM
End Date/Time:	9/26/2017 12:30:00 PM
Last Inspection:	Tuesday, August 15, 2017

Inspector: Karl Houskeeper,

Weather: Clear Skies, Temp. 48 Deg. F.

InspectionID Report Number: 5960

Accepted by: DHADDOCK
10/11/2017

Permitee: **PACIFICORP**
Operator: **INTERWEST MINING CO**
Site: **DEER CREEK MINE**
Address: **PO BOX 310, HUNTINGTON UT 84528**
County: **EMERY**
Permit Type: **PERMANENT COAL PROGRAM**
Permit Status: **ACTIVE**

Current Acreages

20,308.10	**Total Permitted**
91.63	**Total Disturbed**
0.60	**Phase I**
0.60	**Phase II**
0.60	**Phase III**

Mineral Ownership

- [x] Federal
- [x] State
- [ ] County
- [x] Fee
- [ ] Other

Types of Operations

- [x] Underground
- [ ] Surface
- [ ] Loadout
- [ ] Processing
- [ ] Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

At the beginning of the inspection the Division inspector went to the main office located in Huntington Utah. No one could be reached so the inspector conducted the partial inspection un-attended. A voice message was left notifying personnel of the inspectors intentions.

Karl R. Houskeeper

Inspector's Signature:

Date Tuesday, September 26, 2017

Karl Houskeeper,
Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 W North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • *www.ogm.utah.gov*

UTAH DNR OIL, GAS & MINING

Permit Number: C0150018
Inspection Type: PARTIAL
Inspection Date: Tuesday, September 26, 2017

Inspection Continuation Sheet

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. *Substantiate the elements on this inspection by checking the appropriate performance standard.*
   a. *For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.*
   b. *For PARTIAL inspections check only the elements evaluated.*
2. *Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.*
3. *Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.*
4. *Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.*

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	☐	☐	☐	☐
2. Signs and Markers	☑	☐	☑	☐
3. Topsoil	☐	☐	☐	☐
4.a Hydrologic Balance: Diversions	☐	☐	☐	☐
4.b Hydrologic Balance: Sediment Ponds and Impoundments	☐	☐	☐	☐
4.c Hydrologic Balance: Other Sediment Control Measures	☐	☐	☐	☐
4.d Hydrologic Balance: Water Monitoring	☐	☐	☐	☐
4.e Hydrologic Balance: Effluent Limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Disposal of Excess Spoil, Fills, Benches	☐	☐	☐	☐
7. Coal Mine Waste, Refuse Piles, Impoundments	☐	☐	☐	☐
8. Noncoal Waste	☐	☐	☐	☐
9. Protection of Fish, Wildlife and Related Environmental Issues	☐	☐	☐	☐
10. Slides and Other Damage	☐	☐	☐	☐
11. Contemporaneous Reclamation	☐	☐	☐	☐
12. Backfilling And Grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence Control	☐	☐	☐	☐
15. Cessation of Operations	☐	☐	☐	☐
16.a Roads: Construction, Maintenance, Surfacing	☐	☐	☐	☐
16.b Roads: Drainage Controls	☐	☐	☐	☐
17. Other Transportation Facilities	☐	☐	☐	☐
18. Support Facilities, Utility Installations	☐	☐	☐	☐
19. AVS Check	☐	☐	☐	☐
20. Air Quality Permit	☐	☐	☐	☐
21. Bonding and Insurance	☐	☐	☐	☐
22. Other	☑	☐	☑	☐

2. Signs and Markers

The identification signs at the waste rock site and main facility were checked during the inspection. The signs are in compliance with the regulations.

22. Other

Active construction was taking place along side of SR31. The construction is for installation of a pipe line from the Rilda portals to the Huntington Power Plant water storage pond. This pipe line is designed to carry iron laden water from the Rilda portals to the Plant pond to be used in the cooling towers. This will prevent the gravity discharge of water from the portals once the pumps underground are turned off. The gravity discharge will now be conveyed through the pipe line to the plant pond.. Pictures of this construction were taken and are attached to the PDF version of this inspection report.

Rilda to Huntington Power Plant Pipe Line Construction 09/27/2017

Rilda to Huntington Power Plant Pipe Line Construction 09/27/2017

Rilda to Huntington Power Plant Pipe Line Construction 09/27/2017

Rilda to Huntington Power Plant Pipe Line Construction 09/27/2017

Rilda to Huntington Power Plant Pipe Line Construction 09/27/2017

Rilda to Huntington Power Plant Pipe Line Construction 09/27/2017

Rilda to Huntington Power Plant Pipe Line Construction 09/27/2017