



0003

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Revised Copy *Jr*

Jch *sm*
Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, Utah 84143 • 801-538-5340

INSPECTION DATE & TIME: Oct. 26, 1987
9:00 a.m. to 3:00 p.m.

Permittee and/or Operators Name: Utah Power and Light, Mining Division
Business Address: P.O. Box 310 Huntington, UT 84528
Mine Name: Wilberg/Cottonwood Permit Number: ACT/015/019
Type of Mining Activity: Underground Surface Other
County: Emery
Company Official (s): Kurt Snider
State Official(s): Harold G. Sandbeck
Partial: Complete: Date of Last Inspection: Sept. 28&29, 1987
Weather Conditions: Clear, cool
Acreage: Permitted 11508 Disturbed 42.5 Regraded Seeded Bonded 42.5
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	(X)	()	()	(X)
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	(X)	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/019

DATE OF INSPECTION Oct. 26, 1987

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

A partial inspection was conducted with Kurt Snider (UP&L) and Steve Falk (BLM).

1. PERMITS:

UP&L submitted the 1988 East Mountain exploration plan which proposes to drill two (2) exploration drill holes - EM-68 and EM-139, located T.17S., R.7E. in sections 8 and 20, respectively. Concerning EM-68, undersigned inspector spoke to Kirk Synder about the submittal of right-to-enter information to DOGM. Kirk Synder will verify the submittal. The surface owners of EM-68 and EM-136 are Karl A. Seely, Inc. and BLM, respectively. The two drill holes will be drilled to depths varying from 1500 to 1950 feet.

The undersigned inspector encountered no significant environmental concerns with the two (2) proposed drill holes regarding location, hydrology, revegetation or future reclamation. Drill hole EM-68 is located along an existing, but impassable, road, and EM-139 is located on a reclaimed drill access road. Both proposed drill holes are on level ground with no nearby flowing streams.

11. CONTEMPORANEOUS RECLAMATION:

As mentioned above, drill hole EM-139 will be located on a reclaimed drill access road. UP&L had done an excellent job reclaiming the access road.

Copy of this Report:

Mailed to: Val Payne, UP&L; Brian Smith, OSM

Given to: Joe Helfrich, DOGM

Inspectors Signature and Number: Harold G. Sandbeck #27 Date: Nov. 3, 1987