11-15-88 7165 0005

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: November 10, 1988
8:30 am - 11:00 a.m.

Permittee and/or Operators Name: Utah Power & Light Mining Division
Business Address: P.O. Box 310 Huntington, Utah 84528
Mine Name: Wilberg/Cottonwood Permit Number: ACT/015/019
Type of Mining Activity: Underground XX Surface ____ Other _____
County: Emery State: Utah
Company Official(s): Guy Davis
State Official(s): Bill Warmack
Partial: XX Complete: _____ Date of Last Inspection: October 25, 1988
Weather Conditions: Clear and cool
Acreage: Permitted 11508 Disturbed 42.5 Regraded _____ Seeded _____ Bonded 42.5
Enforcement Action: ~~Nov #88-30-5-1~~ None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	( )	( )	( )	( )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	(X)	( )	( )	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	( )	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	( )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	(X)	( )	( )	(X)
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	(X)	( )	( )	(X)

INSPECTION REPORT
(continuation sheet)

PERMIT NUMBER: ACT/015/019 DATE OF INSPECTION November 10, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

Guy Davis (UP&L) accompanied the undersigned inspector during this partial inspection. The abatement of NOV #88-30-5-1 is still pending and Mr. Davis was reminded of the November 30, 1988 deadline.

4b. DIVERSIONS:

1. The installation of the culvert from the upper office to the parking lot has been completed. The outlet may require some protection in the future and this was left to the descretion of the operator.

2. The ditch and culvert inlet by office elevator (parking lot) has been cleaned and appears to be functioning properly.

3. The abatement work required in NOV #88-30-5-1 has not been started as of this date. Mr. Davis is aware of the deadline and work will probably commence shortly.

6. DEVELOPMENT WASTE AND SPOIL DISPOSAL:

Currently, only one remaining cell is available for waste rock disposal at the waste rock site; the previous storage cell is being reclaimed. Depending upon mining conditions the life of the site is not expected to exceed one year.

18. SUPPORT FACILITIES AND UTILITY INSTALLATIONS:

Portions of the upper storage yard are being concreted; eventually the entire yard will be concreted which will enhance drainage flows in this particular area.

Copy of this Report:
Mailed to: Guy Davis, UP&L
Mailed to SLC for: Brian Smith, OSM; Joe Helfrich, DOGM
Filed to: PFO

Inspectors Signature and Number: William A. Warmack #30 Date: Nov. 11, 1988

William A. Warmack 11/11/88