

8-16-88
JCB

0014



Norman H. Bangert
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

355 West North Temple
Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

JCB

INSPECTION DATE & TIME: July 19, 1988
8:30-10:00 a.m.

Permittee and/or Operators Name: Utah Power & Light Mining Division
Business Address: P.O. Box 310 Huntington, Utah 84528
Mine Name: Wilberg/Cottonwood Permit Number: ACT/015/019
Type of Mining Activity: Underground Surface Other
County: Emery State: Utah
Company Official(s): Val Payne
State Official(s): Bill Warmack and Pamela Grubaugh-Littig
Partial: XX Complete: Date of Last Inspection: June 15, 1988
Weather Conditions: Clear and warm
Acreage: Permitted 11508 Disturbed 42.5 Regraded Seeded Bonded 42.5
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	(X)	()	()	(X)
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/019

DATE OF INSPECTION July 19, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

The undersigned inspector was accompanied by Val Payne (UP&L) and Pamela Grubaugh-Littig (DOGM) on this partial inspection. The overall mine site conditions were found to be in good order, with follow-up repairs being completed per the previous inspection (June 15, 1988). Maintenance items listed herein do not constitute a violation of the UMC standards and are listed only as preventive measures.

1. PERMITS:

The operator has submitted a copy of the certificate of liability insurance to the Division as requested.

2. SIGNS AND MARKERS:

Perimeter marker above the storage yard needs repair and will be completed before next inspection.

4b. DIVERSIONS:

The drainage channel from the upper pad to the lower parking lot has been upgraded as requested in previous inspection.

4c. SEDIMENT PONDS AND IMPOUNDMENTS:

Second quarter pond inspections were reviewed and found in good order.

4d. OTHER SEDIMENT CONTROLS:

1. Silt fence below guard shack has been cleaned; material will be taken to waste rock storage area by next inspection.

2. Straw bales across guard shack were in good condition and functioning properly.

3. A silt fence is to be installed in the diversion ditch below the side drainage (south of tipple building); work will be completed before next inspection.

Copy of this Report:

Mailed to: Val Payne, UP&L

Mailed to SLC for: Brian Smith, OSM; Joe Helfrich

Filed to: PFO

Inspectors Signature and Number: William A. Warmack #30 Date: July 21, 1988