0024

File gd on

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/015/019

Inspection Date APRIL 7, 1988

Permittee/Operator Name UTAH POWER & LIGHT COMPANY

Business Address P.O. BOX 310

City HUNTINGTON State UTAH Zip 84528

Mine WILBERG/COTTONWOOD ☐ Surface ☑ Underground ☐ Other

County EMERY State UTAH

Company Official(s) RAY CHRISTENSEN

State Official(s) PAMELA GRUBAUGH-LITTIG

Time of inspection 11:15 ☑ a.m. ☐ p.m. to 12:30 ☐ a.m. ☑ p.m. ☑ Partial ☐ Complete

Date of last inspection MARCH 1, 1988 Weather conditions SUNNY and WARM

Acreage 11,508 ☑ Permitted 42.5 ☑ Disturbed ☐ Regraded ☐ Seeded 42.5 ☑ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☑	☐	☐	☑
2. Signs and markers	☑	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☑	☐	☐	☐
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☑	☐	☐	☑
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☑	☐	☐	☑
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☑	☐	☐	☑
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/019

Inspection Date APRIL 7, 1988

Please number comments to correspond with topics on previous page.

1. The currently mined areas were noted from the mine sequence maps. The longwall is working in the Tenth Right Panel, development work is occurring at the 11th & 12th Right area. Currently the mines are operating on a four day schedule, stockpiles of coal are at a minimum.

I asked Mr. Christensen about UP&L's reply to condition #3 in the Division letter to UP&L dated January 11, 1988 regarding longwall mining of the Ninth and Tenth West longwall panels. He said that UP&L is appealling the entire matter, therefore, until a decision is made in court these conditions will not be addressed. However, UP&L is continuing, as required, subsidence and eagle nest monitoring in the area of question.

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/019

Inspection Date APRIL 7, 1988

Please number comments to correspond with topics on previous page.

8. Used oil is put in 50-gallon drums on site then removed by Pierce Oil in Price. ~~to~~ the ~~the~~ practice of storing on an unpermitted area has been discontinued.

10. UP&L notified the Division of a slide (1/23/88) at the Willberg site. I noted the area where this had occurred. The area has been cleaned up. The rocks were moved to Des-Bee-Dove for rip rap purposes.

16. The drainage by the road from the upper pad to the lower parking area has been recently maintained and is operable.

Copy of report mailed to BRIAN SMITH (OSM) & RAY CHRISTENSEN (UP&L

Copy of report given to Joe Helfrich (DOGM)

Inspector's signature Pamela Grubaugh-Littig No. 20

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

DOGM/IR-2

an equal opportunity employer

11/86 001049