7155 0001

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

RECEIVED
DEC 28 1989
DIVISION OF
OIL, GAS & MINING

pgl gpl

inspection report

Permit No. ACT/015/019

Inspection Date December 18, 1989

Permittee/Operator Name Utah Power & Light Co.

Business Address P.O. Box 310

City Huntington State Ut Zip 84528

Mine Cottonwood Wilberg ☐ Surface ☒ Underground ☐ Other

County Emery State Ut

Company Official(s) J. Val Payne

State Official(s) Bill Malencik

Time of inspection 1:00 ☐ a.m. ☒ p.m. to 3:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 11/29/89 Weather conditions Clear/Cool

Acreage 11508 ☐ Permitted 425 ☐ Disturbed ☐ Regraded ☐ Seeded 425 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☐
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/019

Inspection Date 12/18/89.

Please number comments to correspond with topics on previous page.

General Comments Val Gayne accompanied the undersigned on a partial inspection of the mine and waste rock site. The mine site was dry. Earth moving equipment was operational on site and associated with the first phase of the work on the construction of a second coal silo.

Other Sediment Control. Silt fence was checked next to the the road side leach field.

Sediment Pond. Sediment pond contains water and no problems were noted.

Roads. All roads within the permit area were free from snow and well maintained

Copy of report mailed to { UP&L/Gay Davis
SLC FOR: OSM/Brian Smith; DOGM/Joe Helfrich

Copy of report ~~given~~ filed to PFO

Inspector's signature Tim J Gralinich No. 26

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

12/22/89

DOGM/IR-2

an equal opportunity employer

11/86 001049